

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	OGRID# [229137]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: SRO STATE COM #48H	Facility Type: Flowline	
Surface Owner: State	Mineral Owner:	API No. 30-015-41779

#### LOCATION OF RELEASE

Unit Letter B	Section 07	Township 26S	Range 28E	Feet from the 190'	North/South Line North	Feet from the 2080'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.063797 Longitude 104.1248322

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100bbls	Volume Recovered: 0bbls
Source of Release: 4" Plotline	Date and Hour of Occurrence: 04/21/2017 6:00 pm	Date and Hour of Discovery: 04/21/2017 6:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Bratcher - NMOCD / Ms. Groves - SLO	
By Whom? Robert Grubbs Jr	Date and Hour: 04/22/2017	Time of this email
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 4" polyline had a split due to unknown reason. Cut out the bad section and refused the 4" poly line.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred in the pasture and affected a area of 50' x 100'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Rebecca Haskell	Approved by Environmental Specialist:		
Title: Senior HSE Coordinator	Approval Date:	Expiration Date:	
E-mail Address: <a href="mailto:rhaskell@concho.com">rhaskell@concho.com</a>	Conditions of Approval:		Attached <input type="checkbox"/>
Date: May 1, 2017 Phone: 432-683-7443			

\* Attach Additional Sheets If Necessary