

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico NMOC D Dist 2
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1727250616

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Cottonmouth 23 Federal Com #001H	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner: Federal
API No.: 30-015-39784	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	23	26S	28E	35	North	2310	West	Eddy

Latitude: 32.0351982 Longitude: -104.0590134

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 2bbls oil 10bbls PW	Volume Recovered: 0bbls
Source of Release: Tank failure	Date and Hour of Occurrence: 9/28/2017 12:30pm	Date and Hour of Discovery: 9/28/2017 12:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A fiberglass overflow tank ruptured due to over pressure resulting in the release of approximately 2bbls of oil and 10bbls of produced water. All of the fluid from the release remained within the lined containment.		
Describe Area Affected and Cleanup Action Taken.* The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Sheldon L. Hitchcock</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: <i>M. L. Berman</i>	
Title: HSE Coordinator		Approval Date: 2/22/2018	Expiration Date: N/A
E-mail Address: slhitchcock@concho.com		Conditions of Approval: Like Approval BLM	Attached <input type="checkbox"/>
Date: November 2, 2017 Phone: 575-746-2010			

* Attach Additional Sheets If Necessary

FINAL

2RP-4416