

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received on  
1/24/18  
OCD District 2  
Artesia, NM

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: <b>COG Operating, LLC</b> (OGRID# 229137)	Contact: <b>Robert McNeill</b>
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No.: <b>432-683-7443</b>
Facility Name: <b>HONEY GRAHAM STATE COM #001H</b>	Facility Type: <b>Battery</b>

Surface Owner: State	Mineral Owner: State	API No.: 30-015-37465
----------------------	----------------------	-----------------------

### LOCATION OF RELEASE

Unit Letter D	Section 29	Township 26S	Range 28E	Feet from the 330	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.019516 Longitude: -104.1159668 NAD83

### NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 9 bbls PW; 1 bbls Oil	Volume Recovered: 8.75 bbls PW; 0.75 bbls Oil
Source of Release: Valve	Date and Hour of Occurrence: 1/6/2018 8:00 am	Date and Hour of Discovery: 1/6/2018 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This release occurred when a valve failed on the heater bypass. The valve has been replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release remained within the lined containment. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

 Signature:		<u>OIL CONSERVATION DIVISION</u>	
		Approved by Environmental Specialist: 	
Printed Name: Dakota Neel			
Title: HSE Coordinator		Approval Date: 2/22/18	Expiration Date: N/A
E-mail Address dneel2@concho.com		Conditions of Approval: <b>FINAL</b> Attached <input type="checkbox"/>	
Date: 1/24/2018 Phone: 575-746-2010			

\* Attach Additional Sheets If Necessary

2RP-4566