

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/26/2017

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

njAB1616126496

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No. 575-887-7329
Facility Name: Hasta La Vista 1 DI Federal Com 001H	Facility Type Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42533
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 5	Township 20S	Range 31E	Feet from the 100	North/South Line North	Feet from the 2330	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.609315 Longitude -103.890512

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 9 bbls	Volume Recovered: 0 bbls
Source of Release Flare	Date and Hour of Occurrence: 5/26/16, unknown	Date and Hour of Discovery: 5/26/2016, 10:15 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*
Flare scrubber loaded up causing fluid to exit flare.

Describe Area Affected and Cleanup Action Taken.*
Leak affected 34,600 ft² of pasture to the east of the flare due to high winds. Impacted area was washed down with Micro-Blaze ® on 5/27/2016. Soil samples were retrieved on January 20, 2017 as well as on July 18, 2017. Samples were analyzed at an NMOCD approved laboratory and concentrations of constituents of interest (BTEX, TPH, chloride) were found to be below the recommended remediation action levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Printed Name: Amy Ruth

Title: Environmental Coordinator

Approval Date: 3/20/18

Expiration Date: N/A

E-mail Address: Amy_Ruth@xtoenergy.com

Conditions of Approval: N/A

Attached ☐

Date: 10/26/2017

Phone: 432-661-0571

FINAL

* Attach Additional Sheets If Necessary

2RP-3725