

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DEFERRED

nAB1613953134 Additional Remediation Req OPERATOR ☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Continental A State #001	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No.: 30-015-29696
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	30	17S	29E	330	North	1409	West	Eddy

Latitude: 32.8119583 Longitude: -104.1168976 NAD83

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 10bbls of Oil & 6bls of PW	Volume Recovered: 10bbls of Oil & 4bbls of PW
Source of Release: Steel Flowline	Date and Hour of Occurrence: 5/9/2016 2:45pm	Date and Hour of Discovery: 5/9/2016 2:45pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" steel line corroded due to age. Replaced the corroded section of pipe with a new joint of 3" steel pipe.

Describe Area Affected and Cleanup Action Taken.*

A 20' x 4' area inside of the facilities dike and a 1' x 1' outside of the dike in the pasture were affected by the release. All free fluids were recovered. Concho excavated the impacted area to the extent feasible without threatening the structural integrity of infrastructure. The site will be fully remediated upon abandonment of the facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature: <i>Sheldon Hitchcock</i>		Approved by Environmental Specialist:	
Printed Name: Sheldon L. Hitchcock		ACCEPTED FOR DEFERRAL ONLY	
Title: HSE Coordinator		Accepted 4/3/18	
E-mail Address: slhitchcock@concho.com		Approval Date:	Expiration Date:
Date: 2/13/2018		Conditions of Approval:	Attached <input type="checkbox"/>
Phone: 575-746-2010			

* Attach Additional Sheets If Necessary

Accepted for deferral only - Additional
Remediation efforts required

2RP-3699