

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Rover Operating, LLC	Contact Kirk Faries	
Address 13727 Noel rd. Tower 2 Suite 200 Dallas, TX 75240	Telephone No. 575-513-3198	
Facility Name Atsel Leonard Federal	Facility Type oil production	
Surface Owner BLM	Mineral Owner Rover Operating LLC	API No. N/A

LOCATION OF RELEASE

Unit Letter J	Section 30	Township 17S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.80681 Longitude -104.109197

NATURE OF RELEASE

Type of Release OIL & SALT WATER	Volume of Release 35 BBLs	Volume Recovered 15 BBLs
Source of Release BROKEN WATER LEG ON VESSEL	Date and Hour of Occurrence 9-12-16 APPROX. 4 PM	Date and Hour of Discovery 9-12-16 APPROX. 5 PM
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? CALLED BLM & NMOCD AND LEFT MESSAGES AFTER HOURS, THEN PHONE CALLS NEXT MORNING	
By Whom? KIRK FARIES (PRODUCTION FOREMAN)	Date and Hour 9-12-16 APPROX. 6 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

STORM CAME THROUGH HIGH WINDS CAUSED WATER LEG ON VESSEL TO BREAK RELEASING FLUID. RETRIEVED AS MUCH FLUID AS POSSIBLE HAULED TO DISPOSAL. NEXT DAY NOTIFY BLM & NMOCD ON PHONE GOT PERMISSION TO START REMOVING CONTAMINATED SOIL TO PLASTIC LINER. ONCE SOIL IS REMOVED SAMPLES WILL BE TAKEN TO CARDINAL LABS IN HOBBS, NM. ONCE ALL CONTAMINATION IS REMOVED AND PROPERLY DISPOSED OF WE WILL BACKFILL WITH PROPER SOIL AND RESEED IF NECESSARY. ALL REPAIRS WILL BE MADE TO BATTERY AND BURM BUILT. ALL PAPERWORK WILL BE FILED ACCORDINGLY.


Describe Area Affected and Cleanup Action Taken.*

AFFECTED AT BATTERY THEN RUNS APPROX. 105' SOUTHEAST TO CALICHE ROAD THEN 330' SOUTH ON ROAD. 15 BBLs RECOVERED NIGHT OF SPILL, START REMOVING CONTAMINATED SOIL TO PLASTIC LINER AS OF THIS REPORT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: KIRK FARIES



Printed Name: KIRK FARIES

Approved by Environmental Specialist:

Title: PRODUCTION FOREMAN

Approval Date:

Expiration Date: