

Bratcher, Mike, EMNRD

From: Barnhill, Amy D. <ABarnhill@chevron.com>
Sent: Thursday, March 22, 2018 2:00 PM
To: Weaver, Crystal, EMNRD; Tucker, Shelly
Cc: Bratcher, Mike, EMNRD; Barnhill, Amy D.
Subject: RE: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud
Attachments: Chevron Hayhurst Pad CAP 1.17.18.pdf; P270 Spill 4-17-17.pdf

Crystal and Shelly,

Completions currently has coiled tubing on location rigging up for drill out activities. This activity will take approximately 10 days; being completed around April 1st. After April 1st a remediation crew should be able to start clean-up activities.

In response to the concern raised in the email below regarding the liner; to my knowledge, no one documents or records the exact location of each tear, rip or separation in the liner during routine drilling operations. If major or several significant tears are discovered, the vinyl liner is quickly repaired.

E-tech sampled an area covering 19,202 square feet and results showed hydrocarbon signatures present. I believe full delineation of the spill area will be completed. A site map and corrective action plan are attached, please forward your approval at your earliest convenience.

As soon as the clean-up activity is complete, we will submit a closure report. Please let me know if you have other questions or concerns.

Thank you,

Amy Barnhill, BSEM

HES Environmental Specialist

MCBU

Office: 432-687-7108

Cell: 432-940-8524

E-Mail: ABarnhill@chevron.com

#OurEnvironmentMatters

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Wednesday, March 21, 2018 2:12 PM
To: Tucker, Shelly <stucker@blm.gov>; Barnhill, Amy D. <ABarnhill@chevron.com>
Cc: DeLeon, Josepha <JDxD@chevron.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>; Debeysey, Svetlana <LDebeysey@chevron.com>
Subject: [**EXTERNAL**] RE: Re: Re: Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

RE: Chevron * Hayhurst SO 10 P3 24H * 30-015-43926 * 2RP-4200

Hello all,

I appreciate Shelly asking for an update and I appreciate you all making efforts on meeting her request. However, for how old this release is we really need to see some data and hopefully a closure report on this one. It was stated that the majority of this one stayed within a lined area. We need to see statements that "the liner has been thoroughly inspected and that Chevron attests to the full integrity of the liner area." If any holes or rips are found in the lined area a full report needs to be provided along with a site map with locations of holes/rips marked on the map because a full delineation will be required for all areas where the liner is compromised.

This release occurred almost 1 year ago back on 4/17/17. Please provide all or most of what has been asked for above by no later than 3/30/18.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Tucker, Shelly [<mailto:stucker@blm.gov>]

Sent: Tuesday, March 20, 2018 7:15 AM

To: Barnhill, Amy D. <ABarnhill@chevron.com>

Cc: DeLeon, Josepha <JDxD@chevron.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>; Debeysey, Svetlana <LDebeysey@chevron.com>

Subject: Re: Re: Re: Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

Thank you very much. I will look for your email.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Mon, Mar 19, 2018 at 11:10 AM, Barnhill, Amy D. <ABarnhill@chevron.com> wrote:

Hello Ms Tucker,

My names is Amy and I will be your point of contact for this spill going forward. I have reached out to the company we are working with to get a status update. I will let you know as soon as I receive an answer from them. Please do not hesitate to contact me should you need anything.

Thank you,

Amy Barnhill, BSEM

HES Environmental Specialist

MCBU

Office: 432-687-7108

Cell: 432-940-8524

E-Mail: ABarnhill@chevron.com

#OurEnvironmentMatters

From: Tucker, Shelly [mailto:stucker@blm.gov]

Sent: Thursday, March 15, 2018 5:13 PM

To: Debeysey, Svetlana <LDebeysey@chevron.com>

Cc: DeLeon, Josepha <JDxD@chevron.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>

Subject: [****EXTERNAL****] Re: Re: Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

Was checking on the status of this release.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

575.234.5905 - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Dec 26, 2017 at 10:35 AM, Debeysey, Svetlana <LDebeysey@chevron.com> wrote:

Shelly,

The rig has recently been moved and we were able to schedule delineation sampling and development of the remediation plan. If the weather permits the crew will take delineation samples this week. Once the plan is prepared it will be submitted to Crystal Weaver and yourself at the earliest possible date. Please let us know if there are any concerns.

Happy Holidays!

Lana Debeysey

Field HES Compliance Supervisor

MCBU Midland

O: 432-687-7234

M: 432-258-9584

E-Mail: LDebeysey@chevron.com

[Your CSOC feedback would be appreciated. This feedback will help me have a better understanding of my leadership and CSOC behaviours strengths and improvement opportunities.](#)

From: Tucker, Shelly [mailto:stucker@blm.gov]

Sent: Thursday, December 21, 2017 4:48 PM

To: DeLeon, Josepha <JDxD@chevron.com>

Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Debeysey, Svetlana <LDebeysey@chevron.com>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L

<Nicklois.Leonard@chevron.com>

Subject: [**EXTERNAL**] Re: Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

Wanted to get an update on the status of this release.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

[575.234.5905](#) - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Oct 3, 2017 at 10:27 AM, DeLeon, Josepha <JDxD@chevron.com> wrote:

Shelly / Crystal, I spoke to Mike and explained that the drilling rig is still at this site. As soon as drilling is completed and the rig is moved off remediation will begin according to conditions of approval.

Thank you for your follow up.

From: Tucker, Shelly [mailto:stucker@blm.gov]

Sent: Thursday, September 28, 2017 9:56 AM

To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Cc: DeLeon, Josepha <JDxD@chevron.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Debeysey, Svetlana <LDebeysey@chevron.com>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>

Subject: [**EXTERNAL**] Re: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

What is the status of this release?

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

[575.234.5905](#) - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Sat, Jul 8, 2017 at 2:51 PM, Tucker, Shelly <stucker@blm.gov> wrote:

Thank you for the C-141.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist

O&G Spill/Release Coordinator

Bureau of Land Management

[620 E. Greene St](#)

[Carlsbad, NM 88220](#)

[575.234.5905](#) - Direct

575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Wed, May 17, 2017 at 5:00 PM, Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us> wrote:

Josie,

There were some issues trying to be sure what locational information that was on the C-141 was correct, however, it seems that the coordinates are right cause they match the API location so Olivia forwarded this one on to District II OCD Office. I was not sure if Shelly Tucker had originally been copied on this one or not so I included her.

Also we did get an immediate notification from you on this one to District II. So I am thinking the Initial C-141 just made it to Olivia and Co. in District 1 as a miss shuffle. Either way no biggie just wanted to make sure it is now where it is supposed to be.

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4202.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

[811 S. 1st Street](#)

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Yu, Olivia, EMNRD

Sent: Wednesday, May 3, 2017 1:44 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD

<Crystal.Weaver@state.nm.us>

Subject: FW: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

From: DeLeon, Josepha [<mailto:JDxD@chevron.com>]
Sent: Monday, May 1, 2017 9:24 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Brown, Maxey G, EMNRD <MaxeyG.Brown@state.nm.us>
Cc: Debeysey, Svetlana <LDebeysey@chevron.com>; Meaux, Luke <LukeMeaux@chevron.com>; Leonard, Nicklois L <Nicklois.Leonard@chevron.com>
Subject: Spill - Hayhurst SO 10 P3 24H - Oil Based Mud

Attached is the C-141 for the spill that occurred at Hayhurst SO 10 P3 24 H.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(New Mexico, East Texas and Ft. Stockton Areas)

[1616 W. Bender Blvd.](#)

[Hobbs, NM 88240](#)

[575](#)-263-0424

432-425-1528 - cell

jdx@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker

