

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: RKI Exploration / WPX Energy	Contact: James Raley	
Address: 5315 Buena Vista Dr.	Telephone No: 575-689-7597	
Facility Name: Ross Draw 14	Facility Type: Production Facility	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-25208

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	30	26S	30E	2310	FSL	660	FWL	Eddy

Latitude 32.0124092 Longitude -103.8584137

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 12bbls	Volume Recovered: 12bbls
Source of Release: Wellhead Packing	Date and Hour of Occurrence 02/11/2015 - Unknown	Date and Hour of Discovery 02/12/2015 - Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Tubing and casing valves were closed allowing pressure to build and blow out packing. Well was shut-in, repacked and placed into production. Vac truck dispatched to recover free liquids.		
Describe Area Affected and Cleanup Action Taken.* See attached closure report.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
 Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Jim Raley	Approved by Environmental Specialist:	
Title: Environmental Specialist	Approval Date:	Expiration Date:
E-mail Address: james.ralej@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/24/2018 Phone: 575-689-7597		

* Attach Additional Sheets If Necessary