

Crystal Weaver Environmental Specialist NMOCD District II

January 5, 2018

RE: WPX/RKI * Pinnacle State #2 * 30-015-27071 * 2RP-4492 Plan of Action

Ms. Weaver,

The purpose of this letter is to update our actions and work plan for the Pinnacle State #2 produced water release which occurred on November 2, 2017.

The horizontal extent of the release was immediately mapped with a Trimble GPS Unit (illustrated on attached map). Free liquids were removed with a vac truck of which 13 bbls was recovered from the original release of 18bbl. The impacted area was scraped off to prevent further vertical migration of the salt impacts. The impacted soil was hauled to a disposal facility. After the initial excavation activities were completed, WPX attempted to collect samples to depth from the area of release. Due to hard caliche layer samples were on only able to be collected to a depth of 1', in an area off the well lease road. The results are summarized below and illustrated on attached map and lab results.

Location	Sample ID	DRO (mg/kg)	GRO	ORO (mg/kg)	Benzene	Ethylbenzene	Toluene	Xylenes	Chlorides
Pinnacle #2	S1 at 0'	ND	ND	ND	ND	0.051	ND	0.094	2100
Pinnacle #2	S1 at 1'	ND	ND	ND	ND	ND	ND	ND	780
Pinnacle #2	S2 at 0'	ND	ND	ND	ND	0.056	ND	0.1	4300
Pinnacle #2	S2 at 1'	ND	ND	ND	ND	ND	ND	ND	6200

WPX will secure more robust mechanical sampling equipment capable of collecting additional soil samples at depth throughout the release area, to complete delineation.

Due to lack of available water depth information in this area the site has not been ranked. With collection of additional soil samples, an estimate for depth to groundwater will be established and release area will be ranked.

Please do not hesitate to contact me if you have any questions.


Sincerely,

1 m Kaly

James Raley WPX Energy Environmental Specialist 575-689-7597 james.raley@wpxenergy.com



Scale (absolute) -1:1,250





Pinnacle #2 11/2/2017

Eddy County, NM

811 S. First St., Artesia, NM 88210 Oil Conservation Division Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. 1000 Rio Brazos Road, Aztec, NM 87410 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 RECEIVED Release Notification and Corrective Action	<u>District I</u> 1625 N. French I <u>District II</u>					-	New Mex and Natura	ico ART I Resources N		istrict 2017			Form C-141 d April 3, 2017
DAB:r52.4.501.55 OPERATOR Initial Report Final Report Name of Company: RKI Exploration / WPX Energy #44384 Contact: Karolina Blaney Contact: Karolina Blaney Address: 3513 Buena Vista Dr. Telephone No. 907 058 07613 Telephone No. 907 058 07613 Facility Name: Pinnacle State 2 Facility Type: Lease Road API No. 30- 015-27071 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the Feet from the East/West Line County E 36 22S 28E 1650 FNL 300 FWL Eddy But and Hour of Occurrence Date and Hour of Cocurrence Date and Hour of Occurrence Tage and Hour of Cocurrence Tage and Hour of Cocurrence Tage and Hour of Cocurrence Tage and Hour of Discovery Was Immediate Notice Given? Yes No Not Required Hour 11/3/17 at 11:30 Was and encourse. TYPE of Release: T	<u>District III</u> 1000 Rio Brazos <u>District IV</u>	Road, Aztec	c, NM 87410	5	1220	South	St. Franc	is Dr. 🛛		20	to appropr cordance w	iate Dis rith 19.1	trict Office in 5.29 NMAC.
Name of Company: RKI Exploration / WPX Energy #44384 Contact: Karolina Blaney Address: 3513 Burea Vista Dr. Telephone No. 970 S89 0743 Facility Name: Pinnacle State 2 Facility Type: Lease Road Surface Owner: State Mineral Owner: State API No. 30- 015-27071 Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County E 36 22S 28E 1650 FNL 300 FWL Eddy Latitude: 32.35043_ Longitude -104.04907 NAD83 NATURE OF RELEASE Type of Release: Date and Hour of Occurrence Date and Hour of Discovery Boat and Hour of Counter & Wolme? Hi2/17 18.00 Hi2/17 18.00 Hi2/17 18.00 Was Immediate Notice Given? Yes No Not Required Moor? Occurrence Date and Hour of Discovery Was awatercourse was Impacted, Describe Fully.* No No No No No No No Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poty line which runs along a leas road within a pipeline R				Rel	ease Notific	cation	and Co	orrective A	ction	l			
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County E 36 22S 28E 1650 FNL 330 FWL Eddy Latitude: 32.35043_ Longitude -104.04907 NAD83 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: 11/2/17 11/2/17 11/2/17 18.00 Was Immediate Notice Given? If YES, To Whom? Not MCDC Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whom? Karolina Blaney Date and Hour Of Occurrence Date and Hour Of Course or 11/2/17 at 11.50 Was a Watercourse Reached? Yes IN If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low by trailer) damaged a surface poly line which runs along a leas road within a pieleine ROW. Approximately 18 bbis of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immedia	Name of Co Address: 53	mpany: Rl 15 Buena	KI Explorati Vista Dr.	on / WP2	X Energy 24	,	Contact: Ka Telephone N	rolina Blaney No. 970 589 0743		🛛 Initia	al Report		Final Report
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County E 36 22S 28E 1650 FNL 330 FWL Eddy Latitude: 32.35043_ Longitude -104.04907 NAD83 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: Date and Hour of Occurrence Date and Hour of Discovery 11/2/17 Mammediate Notice Given? If YES, To Whom? Not MCOC Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whom? Karolina Blaney Date and Hour 11/3/17 at 11:50 If a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse Reached? Yes IN NO If YES, Volume Impacting the Watercourse. If a Watercourse as Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbis do if water was spilled out of the compromised line.	Surface Own	ner: State	· · · · · · · · · · · · · · · · · · ·		Mineral C	Owner: S	State			API No	. 30- 015-	27071	
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County E 36 22S 28E 1650 FNL 330 FWL Eddy Latitude: 32.35043_ Longitude -104.04907 NAD83 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: Date and Hour of Occurrence Date and Hour of Discovery 11/2/17 Was Immediate Notice Given? If YES, To Whom? Not Required NMOCD Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whom? Karolina Blaney Date and Hour 10/3/17 at 11:50 If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbis of water was spilled out of the compromised line. Describe Cause of Problem and Remedial Action Taken.* The impacted and was scraped of The impacted sout was hauled to a disposal facility. Baseline samples will be co			<u>₩4 ≜ - </u>		LOC		N OF REI	LEASE					
Latitude: 32.35043_Longitude -104.04907 NAD83 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: Date and Hour of Occurrence Date and Hour of Discovery flowfine 11/2/17 11/2/17 11/2/17 Was Immediate Notice Given? If YES, To Won? NMOCD Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whon? Karolina Blaney Date and Hour 11/3/17 at 11:50 If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was simmediately mapped with a Trimble to delineate the horizontal extent of the impacted and surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was simmediately mapped with a Trimble to delineate the horizontal extent of the impacted and surface water, human health or the environment. The	Unit Letter	Section	Township	Range	Y				East/V	Vest Line	County		
NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: Date and Hour of Occurrence Date and Hour of Discovery flowline 11/2/17 11/2/17 18:00 Was Immediate Notice Given? Yes No Not Required By Whon? Karolina Blaney Date and Hour 11/3/17 at 11:50 Was a Watercourse Reached? Yes Yes No If YES, To Whom? Was a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The inpacted area was simmediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted soil was hauled to a disposal facility. Baseline samples will be collected and sample for TPH. BTEX and Chlorides. Further remediation will be based on the sampling results. 1 hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform correctiv actions for releases which may endanger	E	36	228	28E	1650		FNL	330	I	FWL	Eddy		
NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: Date and Hour of Occurrence Date and Hour of Discovery flowline 11/2/17 11/2/17 18:00 Was Immediate Notice Given? Yes No Not Required By Mhom? Karolina Blaney Date and Hour 11/3/17 at 11:50 Was a Watercourse Reached? Yes Yes No If YES, To Whom? Was a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was simmediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sample for TPH. BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain releases notifications and laceptor or responsibi]	L atitude: 32.35	043 Lo	ongitude -1	04.04907 NAD	83				
Type of Release: Produced Water Volume of Release: 18 bbls Volume Recovered 13 bbls Source of Release: Date and Hour of Occurrence Date and Hour of Discovery flowline 11/2/17 11/2/17 8:00 Was Immediate Notice Given? If YES, To Whom? NMOCD Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whon? Karolina Blaney Date and Hour 11/3/17 at 11:50 If YES, Volume Impacting the Watercourse. If a Watercourse Reached? If YES, Volume Impacting the Watercourse. If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulatinos al operators are reguired to report and/or file ec					NAT	TIRE	OF REL	EASE					
Howline 11/2/17 11/2/17 11/2/17 Was Immediate Notice Given? If YES, To Whom? If YES, To Whom? NMOCD Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whom? Karolina Blaney Date and Hour 11/3/17 at 11:50 NMOCD Crystal Weaver & Michael Bratcher, SLO Amber Groves Was a Watercourse Reached? If Yes X No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was immediately mapped with a trimble to delineate the horizontal extent of the impacts. The line locates were completed and the Clorides. Further remediation will be based on the sampling results. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the op	Type of Relea	se: Produc	ed Water		1 1 2 8 1					Volume I	Recovered 1	3 bbls	
Yes No Not Required NMOCD Crystal Weaver & Michael Bratcher, SLO Amber Groves By Whom? Karolina Blaney Date and Hour 11/3/17 at 11:50 Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was careaded off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of responsibility for compliance with any other federal,		ease:				, <u>,</u>		Iour of Occurrence	e			scovery	
By Whom? Karolina Blaney Date and Hour 11/3/17 at 11:50 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for release which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of inspility for compliance with any other federal, state, or local laws and/or regulations.	Was Immedia	te Notice C		∣Yes Γ	No 🗆 Not R	equired			Michae	Bratcher.	SLO Ambe	er Grove	s
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Mandhing Blaney	By Whom? K	arolina Bla				equireu		-					
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Kareline Blaney			hed?	Yes 🛛	1 No		If YES, Vo	olume Impacting t	the Wate	ercourse.			
N/A Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is mechanical failure. It appears that heavy equipment (i.e. low boy trailer) damaged a surface poly line which runs along a leas road within a pipeline ROW. Approximately 18 bbls of water was spilled out of the compromised line. Describe Area Affected and Cleanup Action Taken.* The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted of was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Markina Blaney Approved by Environmental Specialist:	If a Watercou	rse was Im			-								
The impacted area was immediately mapped with a Trimble to delineate the horizontal extent of the impacts. The line locates were completed and the impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Approved by Environmental Specialist: MAADAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	Describe Cau	this spill is	mechanical fa	ailure. It a	ppears that heavy	equipme led out o	ent (i.e. low b	ooy trailer) damag mised line.	ed a sur	face poly l	ine which r	uns alor	g a leas road
impacted area was scraped off. The impacted soil was hauled to a disposal facility. Baseline samples will be collected and sampled for TPH, BTEX and Chlorides. Further remediation will be based on the sampling results. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Marchine Blaney Signature:	Describe Area	a Affected a	and Cleanup	Action Ta	cen.*				±				
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Approved by Environmental Specialist: Wawadawadawadawadawadawadawadawadawadawa	impacted area	was scrape	ed off. The in	pacted so	il was hauled to a	disposal							
Signature: Karolina Blaney Approved by Environmental Specialist:	regulations al public health should their o or the enviror	l operators or the envir perations h iment. In a	are required t ronment. The ave failed to ddition, NMC	o report a acceptan adequately DCD accept	nd/or file certain i ce of a C-141 repo / investigate and i	release no ort by the remediate	otifications a e NMOCD m e contaminati	nd perform correct arked as "Final R ion that pose a thr	ctive act eport" c reat to g	ions for rel loes not rel round wate	eases which ieve the ope r, surface w	n may en erator of vater, hu	ndanger Liability man health
Approved by Environmental Specialist:		Karolin	a Blane	ч				<u>OIL CON</u>	SERV	ATION	DIVISI		
	Signature:		(1			Approved by	Environmental S	pecialis	ti (M	Be	h	\searrow
Title: Environmental Specialist Approval Date: 11 2017 Expiration Date: N/A							Approval Da	te: 11 20 1	7	Expiration	Date: N	1A	
E-mail Address: Karolina.blaney@wpxenergy.com Conditions of Approval Attached	E-mail Addre	ss: Karolin	a.blaney@wp	xenergy.c	om		Conditions o	f Approval	. 1.	. d	Attache		
Date: 11/17/17 Phone: 970 589 0743 Sel Attach 2222492					9 0743		Sel	/ atta	M	in	1	P	2492
* Attach Additional Sheets If Necessary	Attach Addit	ional She	ets If Necess	ary									

NM OIL CONSERVATION



04-Dec-2017

Karolina Blaney WPX Energy 5315 Buena Vista Dr. Carlsbad, NM 88220

Re: Pinnacle 2

Work Order: 17111499

Dear Karolina,

ALS Environmental received 4 samples on 22-Nov-2017 09:30 AM for the analyses presented in the following report.

The analytical data provided relates directly to the samples received by ALS Environmental and for only the analyses requested.

Sample results are compliant with industry accepted practices and Quality Control results achieved laboratory specifications. Any exceptions are noted in the Case Narrative, or noted with qualifiers in the report or QC batch information. Should this laboratory report need to be reproduced, it should be reproduced in full unless written approval has been obtained from ALS Environmental. Samples will be disposed in 30 days unless storage arrangements are made.

The total number of pages in this report is 15.

If you have any questions regarding this report, please feel free to contact me.

Sincerely,

Electronically approved by: Chad Whelton

Chad Whelton Project Manager

Certificate No: MN 998501

Report of Laboratory Analysis

ADDRESS 3352 128th Ave Holland, Michigan 49424 | PHONE (616) 399-6070 | FAX (616) 399-6185 ALS GROUP USA, CORP Part of the ALS Laboratory Group A Campbell Brothers Limited Company

Environmental 🛄

www.alsglobal.com

RIGHT SOLUTIONS RIGHT PARTNER

Client: Project: Work Order:	WPX Energy Pinnacle 2 17111499			Work Order S	ample Summary
Lab Samp ID (Client Sample ID	<u>Matrix</u>	Tag Number	Collection Date	Date Received Hold
17111499-01 P	innacle 2 S1 0'	Soil		11/20/2017 08:00	11/22/2017 09:30
17111499-02 P	'innacle 2 S1 1'	Soil		11/20/2017 08:05	11/22/2017 09:30 🛛
17111499-03 P	'innacle 2 S2 0'	Soil		11/20/2017 08:10	11/22/2017 09:30
17111499-04 P	'innacle 2 S2 1'	Soil		11/20/2017 08:15	11/22/2017 09:30 🛛

_

QUALIFIERS, ACRONYMS, UNITS

Qualifier	Description
*	Value exceeds Regulatory Limit
**	Estimated Value
a	Analyte is non-accredited
В	Analyte detected in the associated Method Blank above the Reporting Limit
Ε	Value above quantitation range
Н	Analyzed outside of Holding Time
J	Analyte is present at an estimated concentration between the MDL and Report Limit
ND	Not Detected at the Reporting Limit
0	Sample amount is > 4 times amount spiked
Р	Dual Column results percent difference > 40%
R S	RPD above laboratory control limit
S U	Spike Recovery outside laboratory control limits Analyzed but not detected above the MDL
X	Analyte was detected in the Method Blank between the MDL and Reporting Limit, sample results may exhibit background or reagent contamination at the observed level.
Acronym	Description
DUP	Method Duplicate
LCS	Laboratory Control Sample
LCSD	Laboratory Control Sample Duplicate
LOD	Limit of Detection (see MDL)
LOQ	Limit of Quantitation (see PQL)
MBLK	Method Blank
MDL	Method Detection Limit
MS	Matrix Spike
MSD	Matrix Spike Duplicate
PQL	Practical Quantitation Limit
RPD	Relative Percent Difference
TDL	Target Detection Limit
TNTC	Too Numerous To Count
А	APHA Standard Methods
D	ASTM
Е	EPA
SW	SW-846 Update III
Units Reported	Description
% of sample	Percent of Sample
mg/Kg-dry	Milligrams per Kilogram Dry Weight

Date: 04-Dec-17

Client: WPX Energy

Project: Pinnacle 2

Sample ID: Pinnacle 2 S1 0'

Collection Date: 11/20/2017 08:00 AM

Work Order: 17111499 Lab ID: 17111499-01

Matrix: SOIL

Analyses	Result	Qual	Report Limit	Units	Dilution Factor	Date Analyzed
DIESEL RANGE ORGANICS BY GC-F	ID		SW801	5C P	rep: SW3546 11/28/17 14:00) Analyst: KB
DRO (C10-C28)	ND		5.2	mg/Kg-dr	y 1	11/29/2017 12:42 PM
ORO (C28-C40)	ND		5.2	mg/Kg-dr	y 1	11/29/2017 12:42 PM
Surr: 4-Terphenyl-d14	44.0		34-130	%REC	1	11/29/2017 12:42 PM
GASOLINE RANGE ORGANICS BY G	C-FID		SW801	5D P	rep: SW5035 11/27/17 13:48	Analyst: KB
GRO (C6-C10)	ND		5.6	mg/Kg-dr	y 1	11/28/2017 07:29 AM
Surr: Toluene-d8	92.0		71-123	%REC	1	11/28/2017 07:29 AM
VOLATILE ORGANIC COMPOUNDS			SW826	0B P	rep: SW5035 11/27/17 13:46	Analyst: WH
Benzene	ND		0.034	mg/Kg-dr	y 1	11/29/2017 07:27 AM
Ethylbenzene	0.051		0.034	mg/Kg-d	ry 1	11/29/2017 07:27 AM
m,p-Xylene	0.094		0.068	mg/Kg-d	ry 1	11/29/2017 07:27 AM
o-Xylene	ND		0.034	mg/Kg-dr	y 1	11/29/2017 07:27 AM
Toluene	ND		0.034	mg/Kg-dr	y 1	11/29/2017 07:27 AM
Xylenes, Total	ND		0.10	mg/Kg-dr	y 1	11/29/2017 07:27 AM
Surr: 1,2-Dichloroethane-d4	101		70-130	%REC	1	11/29/2017 07:27 AM
Surr: 4-Bromofluorobenzene	101		70-130	%REC	1	11/29/2017 07:27 AM
Surr: Dibromofluoromethane	83.8		70-130	%REC	1	11/29/2017 07:27 AM
Surr: Toluene-d8	97.1		70-130	%REC	1	11/29/2017 07:27 AM
CHLORIDE			A4500-	CL C-11 P	rep: EXTRACT 12/1/17 14:4	5 Analyst: JB
Chloride	2,100		32	mg/Kg-d	ry 1	12/1/2017 03:45 PM
MOISTURE Moisture	6.0		SW355 0.050	0C % of sam	iple 1	Analyst: NW 11/29/2017 03:50 PM

Client: WPX Energy

Project: Pinnacle 2

Sample ID: Pinnacle 2 S1 1'

Collection Date: 11/20/2017 08:05 AM

Work Order: 17111499 Lab ID: 17111499-02

Matrix: SOIL

Analyses	Result	Qual	Report Limit	Units	Dilution Factor	Date Analyzed
DIESEL RANGE ORGANICS BY GC-FID			SW801	5C	Prep: SW3546 11/28/17 14:0	0 Analyst: KB
DRO (C10-C28)	ND		5.1	mg/Kg-o	dry 1	11/29/2017 01:11 AM
ORO (C28-C40)	ND		5.1	mg/Kg-o	dry 1	11/29/2017 01:11 AM
Surr: 4-Terphenyl-d14	52.1		34-130	%REC	1	11/29/2017 01:11 AM
GASOLINE RANGE ORGANICS BY GC-	FID		SW801	5D	Prep: SW5035 11/27/17 13:4	⁸ Analyst: KB
GRO (C6-C10)	ND		5.4	mg/Kg-o	dry 1	11/28/2017 07:55 AM
Surr: Toluene-d8	90.3		71-123	%REC	1	11/28/2017 07:55 AM
VOLATILE ORGANIC COMPOUNDS			SW826	0B	Prep: SW5035 11/27/17 13:4	6 Analyst: WH
Benzene	ND		0.033	mg/Kg-o	dry 1	11/29/2017 07:42 AM
Ethylbenzene	ND		0.033	mg/Kg-o	dry 1	11/29/2017 07:42 AM
m,p-Xylene	ND		0.065	mg/Kg-o	dry 1	11/29/2017 07:42 AM
o-Xylene	ND		0.033	mg/Kg-o	dry 1	11/29/2017 07:42 AM
Toluene	ND		0.033	mg/Kg-o	dry 1	11/29/2017 07:42 AM
Xylenes, Total	ND		0.098	mg/Kg-o	dry 1	11/29/2017 07:42 AM
Surr: 1,2-Dichloroethane-d4	99.8		70-130	%REC	1	11/29/2017 07:42 AM
Surr: 4-Bromofluorobenzene	98.6		70-130	%REC	1	11/29/2017 07:42 AM
Surr: Dibromofluoromethane	82.4		70-130	%REC	1	11/29/2017 07:42 AM
Surr: Toluene-d8	97.8		70-130	%REC	1	11/29/2017 07:42 AM
CHLORIDE			A4500-	CL C-11	Prep: EXTRACT 12/1/17 14:4	⁵ Analyst: JB
Chloride	780		31	mg/Kg-	dry 1	12/1/2017 03:45 PM
MOISTURE Moisture	4.2		SW355 0.050	0C % of sa	mple 1	Analyst: NW 11/29/2017 03:50 PM

Client: WPX Energy

Project: Pinnacle 2

Sample ID: Pinnacle 2 S2 0'

Collection Date: 11/20/2017 08:10 AM

Work Order: 17111499 Lab ID: 17111499-03

Matrix: SOIL

Analyses	Result	Qual	Report Limit	Units	Dilution Factor	Date Analyzed
DIESEL RANGE ORGANICS BY GC-F	ID		SW801	5C P	rep: SW3546 11/28/17 14:00	Analyst: KB
DRO (C10-C28)	ND		5.3	mg/Kg-dr	y 1	11/29/2017 01:40 AM
ORO (C28-C40)	ND		5.3	mg/Kg-dr	y 1	11/29/2017 01:40 AM
Surr: 4-Terphenyl-d14	40.0		34-130	%REC	1	11/29/2017 01:40 AM
GASOLINE RANGE ORGANICS BY G	C-FID		SW801	5D P	rep: SW5035 11/27/17 13:48	Analyst: KB
GRO (C6-C10)	ND		5.8	mg/Kg-dr	y 1	11/28/2017 08:21 AM
Surr: Toluene-d8	92.7		71-123	%REC	1	11/28/2017 08:21 AM
VOLATILE ORGANIC COMPOUNDS			SW826	0B Pi	rep: SW5035 11/27/17 13:46	Analyst: WH
Benzene	ND		0.035	mg/Kg-dr	y 1	11/29/2017 07:58 AM
Ethylbenzene	0.056		0.035	mg/Kg-dı	y 1	11/29/2017 07:58 AM
m,p-Xylene	0.10		0.070	mg/Kg-dı	y 1	11/29/2017 07:58 AM
o-Xylene	ND		0.035	mg/Kg-dr	y 1	11/29/2017 07:58 AM
Toluene	ND		0.035	mg/Kg-dr	y 1	11/29/2017 07:58 AM
Xylenes, Total	ND		0.10	mg/Kg-dr	y 1	11/29/2017 07:58 AM
Surr: 1,2-Dichloroethane-d4	101		70-130	%REC	1	11/29/2017 07:58 AM
Surr: 4-Bromofluorobenzene	99.0		70-130	%REC	1	11/29/2017 07:58 AM
Surr: Dibromofluoromethane	83.8		70-130	%REC	1	11/29/2017 07:58 AM
Surr: Toluene-d8	97.8		70-130	%REC	1	11/29/2017 07:58 AM
CHLORIDE			A4500-	CL C-11 P	rep: EXTRACT 12/1/17 14:4	Analyst: JB
Chloride	4,300		33	mg/Kg-dı	y 1	12/1/2017 03:45 PM
MOISTURE Moisture	7.4		SW355 0.050	0C % of sam	ple 1	Analyst: NW 11/29/2017 03:50 PM

Client: WPX Energy

Project: Pinnacle 2

Sample ID: Pinnacle 2 S2 1'

Collection Date: 11/20/2017 08:15 AM

Work Order: 17111499 Lab ID: 17111499-04

Matrix: SOIL

Analyses	Result	Qual	Report Limit	Units	Dilution Factor	Date Analyzed
DIESEL RANGE ORGANICS BY GC-FID			SW801	5C Pre	ep: SW3546 11/28/17 14:00	Analyst: KB
DRO (C10-C28)	ND		5.4	mg/Kg-dry	1	11/29/2017 02:09 AM
ORO (C28-C40)	ND		5.4	mg/Kg-dry	1	11/29/2017 02:09 AM
Surr: 4-Terphenyl-d14	40.5		34-130	%REC	1	11/29/2017 02:09 AM
GASOLINE RANGE ORGANICS BY GC-	ID		SW801	5D Pre	ep: SW5035 11/27/17 13:48	Analyst: KB
GRO (C6-C10)	ND		6.0	mg/Kg-dry	1	11/28/2017 09:40 AM
Surr: Toluene-d8	93.2		71-123	%REC	1	11/28/2017 09:40 AM
VOLATILE ORGANIC COMPOUNDS			SW826	0B Pre	ep: SW5035 11/27/17 13:46	Analyst: AK
Benzene	ND		0.036	mg/Kg-dry	1	11/30/2017 05:13 AM
Ethylbenzene	ND		0.036	mg/Kg-dry	1	11/30/2017 05:13 AM
m,p-Xylene	ND		0.072	mg/Kg-dry	1	11/30/2017 05:13 AM
o-Xylene	ND		0.036	mg/Kg-dry	1	11/30/2017 05:13 AM
Toluene	ND		0.036	mg/Kg-dry	1	11/30/2017 05:13 AM
Xylenes, Total	ND		0.11	mg/Kg-dry	1	11/30/2017 05:13 AM
Surr: 1,2-Dichloroethane-d4	101		70-130	%REC	1	11/30/2017 05:13 AM
Surr: 4-Bromofluorobenzene	96.0		70-130	%REC	1	11/30/2017 05:13 AM
Surr: Dibromofluoromethane	85.6		70-130	%REC	1	11/30/2017 05:13 AM
Surr: Toluene-d8	97.1		70-130	%REC	1	11/30/2017 05:13 AM
CHLORIDE			A4500-	CL C-11 Pre	ep: EXTRACT 12/1/17 14:45	Analyst: JB
Chloride	6,200		33	mg/Kg-dry	/ 1	12/1/2017 03:45 PM
MOISTURE Moisture	9.1		SW355 0.050	0C % of sam	ble 1	Analyst: NW 11/29/2017 03:50 PM

Client:	WPX Energy
Work Order:	17111499
Project:	Pinnacle 2

QC BATCH REPORT

Batch ID: 111060	Instrument ID GC	В		Metho	d: SW80	15C						
MBLK	Sample ID: DBLKS1-11	1060-1110	060			ι	Jnits: mg/	Kg	Analysi	s Date: 11	1/28/2017	04:58 PM
Client ID:		Run ID	: GC8_17	71128A		Se	qNo: 478 2	2809	Prep Date: 11/2	8/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
		ND										
DRO (C10-C28) ORO (C28-C40)		ND	5.0 5.0									
Surr: 4-Terphenyl	-d14	2.4	0	3.33		0	72.1	34-130	0			
LCS	Sample ID: DLCSS1-11	1060-1110)60			ι	Jnits: mg/	Kg	Analysi	s Date: 11	1/28/2017	05:27 PM
Client ID:		Run ID	: GC8_17	71128A		Se	qNo: 478 2	2811	Prep Date: 11/2	8/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
DRO (C10-C28)		335	5.0	333		0	101	65-122	0			
ORO (C28-C40)		334	5.0	333		0	100	81-116	0			
Surr: 4-Terphenyl	-d14	2.483	0	3.33		0	74.6	34-130	0			
MS	Sample ID: 17111497-0	2A MS				ι	Jnits: mg/	Kg	Analysi	s Date: 11	1/28/2017	06:25 PM
Client ID:		Run ID	: GC8_17	71128A		Se	qNo: 478 2	2814	Prep Date: 11/2	8/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
DRO (C10-C28)		342.1	5.0	331.3		0	103	65-122	0			
ORO (C28-C40)		346.1	5.0	331.3	7.5	26	102	81-116	0			
Surr: 4-Terphenyl	-d14	2.553	0	3.313		0	77.1	34-130	0			
MSD	Sample ID: 17111497-0	2A MSD				ι	Jnits: mg/	Kg	Analysi	s Date: 11	1/28/2017	06:54 PM
Client ID:		Run ID	: GC8_17	71128A		Se	qNo: 478 2	2815	Prep Date: 11/2	8/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
DRO (C10-C28)		323.9	5.0	330.3		0	98.1	65-122	342.1	5.48	30	
ORO (C28-C40)		341	5.0	330.3	7.5	26	101	81-116	346.1	1.5	30	
Surr: 4-Terphenyl	-d14	2.43	0	3.303		0	73.6	34-130	2.553	4.94	30	
The following samp	oles were analyzed in this	s batch:	01	7111499-		7111 2A	499-	17 03	111499- A			

Client: Work Order: Project:	WPX Energy 17111499 Pinnacle 2							QC	BATC	H REI	PORT
Batch ID: 111034	Instrument ID GC10		Metho	d: SW801	5D						
MBLK	Sample ID: MBLK-111034-11	11034			U	nits: µg/k	(g-dry	Analys	sis Date: 11	1/27/2017	07:22 PM
Client ID:	R	un ID: GC10_	_171127A		Sec	qNo: 478 2	2664	Prep Date: 11/	27/2017	DF: 1	
Analyte	Resu	ılt PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
GRO (C6-C10) Surr: Toluene-d8	N 455	-,	5000		0	91.2	71-123	C)		
LCS	Sample ID: LCS-111034-111	034			U	nits: µg/k	(g-dry	Analys	sis Date: 11	/27/2017	06:04 PM
Client ID:	R	un ID: GC10_	_171127A		Sec	qNo: 478 2	2662	Prep Date: 11/	27/2017	DF: 1	
Analyte	Resu	ılt PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
GRO (C6-C10)	49560	0 5,000	500000		0	99.1	71-123	C	1		
Surr: Toluene-d8	509	92 0	5000		0	102	71-123	C	1		
MS	Sample ID: 17111505-01A M	S			U	nits: µg/k	(g-dry	Analys	sis Date: 11	1/28/2017	03:18 PM
Client ID:	R	un ID: GC10	_171127A		Sec	qNo: 478 2	2702	Prep Date: 11/	27/2017	DF: 1	
Analyte	Resu	ılt PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
GRO (C6-C10)	55010	0 5,600	557100		0	98.7	71-123	C	1		
Surr: Toluene-d8	540	06 0	5571		0	97	71-123	C)		
MSD	Sample ID: 17111505-01A M	SD			U	nits: µg/k	(g-dry	Analys	sis Date: 11	1/28/2017	03:44 PM
Client ID:	R	un ID: GC10_	_171127A		Sec	qNo: 478 2	2703	Prep Date: 11/	27/2017	DF: 1	
Analyte	Resu	ılt PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
GRO (C6-C10)	55990	0 5,600	557100		0	101	71-123	550100	1.78	30	
Surr: Toluene-d8	547	75 0	5571		0	98.3	71-123	5406	1.26	30	
The following sam	oles were analyzed in this bate	C 1	7111499- 01A 17111499- 04A	17 02	71114 2A	499-	17 03	111499- A			

QC BATCH REPORT

Batch ID: 111033

Instrument ID VMS10

Method: SW8260B

MBLK	Sample ID: MBLK-1110	33-111033				Units: µg	/Kg-dry		Analys	sis Date:	11/29/2017	02:47 A
Client ID:		Run ID:	VMS10	_171128B		SeqNo: 47	83450	Prep Da	ate: 11/	27/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%REC	Control Limit	RPD Va	Ref lue	%RPD	RPD Limit	Qual
Benzene		ND	30									
Ethylbenzene		ND	30									
m,p-Xylene		ND	60									
o-Xylene		ND	30									
Toluene		ND	30									
Xylenes, Total		ND	90									
Surr: 1,2-Dichloroeth	ane-d4	1012	0	1000		0 101	70-130		C)		
Surr: 4-Bromofluorob	penzene	992.5	0	1000		0 99.2	70-130	1	C)		
Surr: Dibromofluoron	nethane	867	0	1000		0 86.7	70-130		C)		
Surr: Toluene-d8		975	0	1000		0 97.5	70-130	1	C)		

LCS	Sample ID: LCS-111033	-111033					Units: µg/k	(g-dry		Analy	/sis Date:	11/29/2017	02:00 A
Client ID:		Run ID:	VMS10	_171128B		S	eqNo: 478 :	3449	Prep D	ate: 11	/27/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ret Value	F	%REC	Control Limit		D Ref alue	%RPD	RPD Limit	Qual
Benzene		1090	30	1000		0	109	75-125			0		
Ethylbenzene		960.5	30	1000		0	96	75-125			0		
m,p-Xylene		1888	60	2000		0	94.4	80-125			0		
o-Xylene		948.5	30	1000		0	94.8	75-125			0		
Toluene		1082	30	1000		0	108	70-125			0		
Xylenes, Total		2836	90	3000		0	94.6	75-125			0		
Surr: 1,2-Dichloroet	hane-d4	968.5	0	1000		0	96.8	70-130			0		
Surr: 4-Bromofluoro	benzene	1042	0	1000		0	104	70-130			0		
Surr: Dibromofluoro	methane	996.5	0	1000		0	99.6	70-130			0		
Surr: Toluene-d8		995.5	0	1000		0	99.6	70-130			0		

MS	Sample ID: 17111505-0			ι	Jnits: µg/ŀ	(g-dry	An	Analysis Date: 11/29/2017 08:14					
Client ID:		Run ID	VMS10	_171128B		Se	eqNo: 478	3468	Prep Date:	11/27/2	2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Re Value	-	6RPD	RPD Limit	Qual
Benzene		1221	33	1114		0	110	75-125		0			
Ethylbenzene		1017	33	1114		0	91.3	75-125		0			
m,p-Xylene		2030	67	2228		0	91.1	80-125		0			
o-Xylene		1016	33	1114		0	91.2	75-125		0			
Toluene		1138	33	1114		0	102	70-125		0			
Xylenes, Total		3046	100	3342		0	91.1	75-125		0			
Surr: 1,2-Dichloroe	thane-d4	1094	0	1114		0	98.2	70-130		0			
Surr: 4-Bromofluor	obenzene	1200	0	1114		0	108	70-130		0			
Surr: Dibromofluoro	omethane	1042	0	1114		0	93.5	70-130		0			
Surr: Toluene-d8		1092	0	1114		0	98	70-130		0			

Note:

Instrument ID VMS10

Method: SW8260B

MSD	Sample ID: 17111505-0	01A MSD	Units: µg/Kg-dry				Analysis Date: 11/29/2017 08:29						
Client ID:		Run ID: VMS10_171128B				SeqNo: 4783469			Prep Date: 11/27/2017			DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value		%REC	Control Limit	RPD Ref Value	Q	%RPD	RPD Limit	Qual
Benzene		1267	33	1114		0	114	75-125	12	21	3.76	30	
Ethylbenzene		1083	33	1114		0	97.2	75-125	10	17	6.26	30	
m,p-Xylene		2127	67	2228		0	95.5	80-125	20	30	4.69	30	
o-Xylene		1066	33	1114		0	95.7	75-125	10	16	4.87	30	
Toluene		1188	33	1114		0	107	70-125	11	38	4.31	30	
Xylenes, Total		3194	100	3342		0	95.6	75-125	30	46	4.75	30	
Surr: 1,2-Dichloroeth	hane-d4	1089	0	1114		0	97.7	70-130	10	94	0.46	30	
Surr: 4-Bromofluorol	benzene	1241	0	1114		0	111	70-130	12	00	3.38	30	
Surr: Dibromofluoror	methane	1062	0	1114		0	95.4	70-130	10	42	1.96	30	
Surr: Toluene-d8		1098	0	1114		0	98.6	70-130	10	92	0.509	30	
The following sample	s were analyzed in thi	is batch:	17 01	'111499- A		7111 2A	499-	171 03/	11499- \				

01A 17111499-04A

Client: Work Order: Project:	WPX Energy 17111499 Pinnacle 2							QC	C BATC	H REI	PORT
Batch ID: 111279	Instrument ID WE	TCHEM		Metho	d: A4500	-CI C-11					
MBLK	Sample ID: MBLK-1112	279-111279)			Units: mg/	Kg	Anal	ysis Date: 1	2/1/2017 0	3:45 PM
Client ID:		Run ID	WETCH	HEM_17120	1L	SeqNo: 478	8677	Prep Date: 1	2/1/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Chloride		ND	30								
LCS	Sample ID: LCS-11127	9-111279				Units: mg/	Kg	Anal	ysis Date: 1	2/1/2017 0	3:45 PM
Client ID:		Run ID	WETCH	HEM_17120	1L	SeqNo: 478	8678	Prep Date: 1	2/1/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Chloride		519.8	30	500		0 104	87-112		0		
MS	Sample ID: 17111502-0)3A MS				Units: mg/	Kg	Anal	ysis Date: 1	2/1/2017 0	3:45 PM
Client ID:		Run ID	WETCH	HEM_17120	1L	SeqNo: 478	8686	Prep Date: 1	2/1/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Chloride		8231	30	502	76	22 121	87-112		0		SO
MSD	Sample ID: 17111502-0	3A MSD				Units: mg/	Kg	Anal	ysis Date: 1	2/1/2017 0	3:45 PM
Client ID:		Run ID	WETCH	HEM_17120	1L	SeqNo: 478	8687	Prep Date: 1	2/1/2017	DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%REC	Control Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Chloride		8165	30	498	76	22 109	87-112	823	31 0.8	10	0
The following sam	nples were analyzed in thi	s batch:	01 17	7111499- 1A 7111499- 4A		7111499- 2A	17 03	'111499- 3A			

Client: Work Order: Project:	WPX Energy 17111499 Pinnacle 2							QC	BATC	H RE	PORT
Batch ID: R225482	Instrument ID MC	DIST		Metho	d: SW35 5	50C					
MBLK	Sample ID: WBLKS-R2	225482				Units: %	of sample	Analy	sis Date: 1	1/29/2017	03:50 PM
Client ID:		Run ID	: MOIST	_171129C		SeqNo: 47	84962	Prep Date:		DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%RE0	Control C Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Moisture		ND	0.050								
LCS	Sample ID: LCS-R2254	482				Units: %	of sample	e Analy	sis Date: 1	1/29/2017	03:50 PM
Client ID:		Run ID	: MOIST	_171129C		SeqNo: 47	84961	Prep Date:		DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%RE0	Control C Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Moisture		100	0.050	100		0 100	99.5-100).5 ()		
DUP	Sample ID: 17111461-2	22B DUP				Units: %	of sample	e Analy	sis Date: 1	1/29/2017	03:50 PM
Client ID:		Run ID	: MOIST	_171129C		SeqNo: 47	84945	Prep Date:		DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%RE0	Control C Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Moisture		23.58	0.050	0		0 0	0-0	23	3 2.49	5	
DUP	Sample ID: 17111500-0	01A DUP				Units: %	of sample	e Analy	sis Date: 1'	1/29/2017	03:50 PM
Client ID:		Run ID	: MOIST	_171129C		SeqNo: 47	84956	Prep Date:		DF: 1	
Analyte		Result	PQL	SPK Val	SPK Ref Value	%RE0	Control C Limit	RPD Ref Value	%RPD	RPD Limit	Qual
Moisture		58.43	0.050	0		0 0	0-0	58.36	6 0.12	5	
The following sam	ples were analyzed in th	is batch:	01 17	7111499- 1A 7111499- 4A		7111499- 2A		7111499- 3A			

ALS Laboratory Group

Chain-of-Custody

LS)

	Houston TX		Chain-or-C						εοα	У		Form 202r8				12r8	V	WORKORDER #		۱ ۲		11	19	9	1	
(ALS)		SA	MPLER					• • • • • • •			D	ATE		11/2	1/201					PAG	E	1		of	1	
PROJECT NAME	Pinnacle 2		SITE ID	Pinnac	cle 2					TURN	IARO	UND		5	day				DIS	POSA	Lab		or	Ret	urn to (Client
PROJECT No.		EDD FO	ORMAT												Τ	T	Τ			Т						T
		PURCHASE	ORDER																							
COMPANY NAME	WPX Energy	BILL TO CO	MPANY	WPX I	Energy																					
SEND REPORT TO	Blaney	INVOICE AT		Karolir	na Blaney																					
ADDRESS		AD	DRESS	5315 E	Buena Vista D	r																				
CITY / STATE / ZIP		CITY / STAT	TE / ZIP	Carlsb	ad, NM 88220	0																				
PHONE			PHONE	970 58	39 0743				þ																	
FAX			FAX						ÖŤ																	
E-MAIL	Karolina.blaney@wpxenergy.com; james.raley@wpxenergy.com		E-MAIL	<u>Karolir</u> James	na.blaney@wj s.Raley@wpxe	oxenerg energy.c	<u>v.com;</u> om		DRO+GRO+ORO	втех	Chlorides															
Lab ID	Field ID	Matrix	Sam Dat		Sample Time	# Bottles	Pres.	QC																		
1	Pinnacle 2 S1 0'	s	11/20/	2017	8:00	2	8	x	x	x	x		· · · · · · · · · · · · · · · · · · ·								-					
2	Pinnacle 2 S1 1'	s	11/20/	2017	8:05	2	8	x	x	x	x															
3	Pinnacle 2 S2 0'	s	11/20/	2017	8:10	2	8	x	×	x	x															
<u> </u>	Pinnacle 2 S2 1'	S	11/20/	2017	8:15	2	8	x	x	x	x															
																		Τ								
																						1				

*Time Zone (Circle): EST CST MST PST Matrix: O = oil S = soil NS = non-soil solid W = water L = liquid E = extract F = filter

For metals or ani	ions, please detail analytes below.					SIGNATURE	PRINTED NAME	DATE	TIME
Comments:		QC PAC	KAGE (check below)	Γ	RELINQUISHED BY	Kanline Bhaney	Karolina Blaney	11/21/2017	15:00
		х	LEVEL II (Standard QC)		RECEIVED BY	Nicoli Field	NICOL Frederic	611-22-17	0930
			LEVEL III (Std QC + forms)	Γ	RELINQUISHED BY			7	
	\bigcirc		LEVEL IV (Std QC + forms + raw data)	Γ	RECEIVED BY				
				Γ	RELINQUISHED BY				
Preservative Key:	1-HCI 2-HNO3 3-H2SO4 4-NaOH 5-NaHSO4 7-Oth	эг 8-4	degrees C 9-5035	Γ	RECEIVED BY				
				-			~ /		

Sample Receipt Checklist

Client Name: WPX - NM		Dat	e/Time F	Received:	22-Nov-17	7 09:30	
Work Order: 17111499		Rec	ceived by	/:	<u>NCF</u>		
Checklist completed by Nicole Fredericks 2	22-Nov-17 Date	Review	ed by:	<i>Chael Wh</i> eSignature	elton		27-Nov-17 Date
Matrices: Soil Carrier name: FedEx							I
Shipping container/cooler in good condition?	Yes	✓	No	Not Prese	ent 🗌		
Custody seals intact on shipping container/cooler?	Yes		No 🗌	Not Prese	ent 🗌		
Custody seals intact on sample bottles?	Yes		No 🗌	Not Prese	ent 🗹		
Chain of custody present?	Yes	 Image: A start of the start of	No 🗌				
Chain of custody signed when relinquished and received?	Yes		No 🗌				
Chain of custody agrees with sample labels?	Yes	 Image: A start of the start of	No 🗌				
Samples in proper container/bottle?	Yes		No 🗌				
Sample containers intact?	Yes		No 🗌				
Sufficient sample volume for indicated test?	Yes	✓	No 🗌				
All samples received within holding time?	Yes	✓	No 🗌				
Container/Temp Blank temperature in compliance?	Yes		No 🗌				
Sample(s) received on ice? Temperature(s)/Thermometer(s):	Yes 4.4/4.4		No	SR	2	I	
Cooler(s)/Kit(s):							
Date/Time sample(s) sent to storage:)1712:26:39					
Water - VOA vials have zero headspace?	Yes		No	No VOA vials	submitted	\checkmark	
Water - pH acceptable upon receipt?	Yes	✓	No 🗌	N/A			
pH adjusted? pH adjusted by:	Yes		No 🗹	N/A			

Login Notes:

Client Contacted:	Date Contacted:	Person Contacted:	
Contacted By:	Regarding:		
Comments:			
CorrectiveAction:			
			SR