

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/22/2018

NMOCD Dist 2

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1527856976

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy	Contact Kyle Littrell
Address 3104 E Greene Street Carlsbad, N.M. 88220	Telephone No. 432-221-7331
Facility Name James Ranch Unit #16	Facility Type Exploration and Production

Surface Owner State	Mineral Owner State	API No. 30-015-28623
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 36	Township 22S	Range 30E	Feet from the 1980	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.350408 Longitude -103.826691 NAD83

NATURE OF RELEASE

Type of Release Produced Water and crude oil	Volume of Release 1.5 bbls oil 8.5 bbl PW	Volume Recovered 1 bbls oil 7 bbl PW
Source of Release wellhead stuffing box	Date and Hour of Occurrence 10/1/2016 time unknown	Date and Hour of Discovery 10/1/2015 1pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*



Packing in stuffing box failed. E-pot shut down the well and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

Leak affected 1872 square feet including caliche pad and a small edge of pasture bordering the north side of the pad. Vacuum truck recovered standing fluids.

Initial site sampling indicated 4 of 5 samples did not exceed NMOCD action levels for BTEX, TPH, and Chloride. The impacted soil identified in one soil sample (SS5) was excavated and a confirmation soil sample (SS6A) was collected from the excavation on March 23, 2018. Laboratory analytical results from the confirmation sample indicate concentrations of BTEX, TPH, and chloride do not exceed NMOCD remediation action levels. XTO requests no further action for this release and will backfill and re-contour the excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<u>OIL CONSERVATION DIVISION</u>	
Signature: 	Approved by Environmental Specialist 
Printed Name: Kyle Littrell	
Title: SH&E Coordinator	Approval Date: 5/22/2018 Expiration Date: N/A
E-mail Address: Kyle_Littrell@xtoenergy.com	Conditions of Approval: N/A
Date: 5/15/2018 Phone: 432-221-7331	Attached <input type="checkbox"/>
FINAL	

* Attach Additional Sheets If Necessary

2RP-3315