Bratcher, Mike, EMNRD

From: Wade_Dittrich@oxy.com

Sent: Tuesday, April 3, 2018 7:13 AM

To: stucker@blm.gov

Cc: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; ben@trinityoilfieldservices.com;

duskie@trinityoilfieldservices.com; todd@trinityoilfieldservices.com

Subject: RE: Re: NEL 4 SWD Battery

Shelly,

The date on the Initial notification is correct. Sorry about the confusion.

Wade Dittrich

Environmental Specialist

Oxy Permian-New Mexico

575-390-2828 cell 575-397-8214 office

Wade_Dittrich@Oxy.com

From: Tucker, Shelly [mailto:stucker@blm.gov]

Sent: Friday, March 30, 2018 8:37 AM


To: Dittrich, John W < Wade_Dittrich@oxy.com>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Ben J. Arguijo <ben@trinityoilfieldservices.com>; Duskie Bennett <duskie@trinityoilfieldservices.com>; Todd Roberson

<todd@trinityoilfieldservices.com>

Subject: [EXTERNAL] Re: NEL 4 SWD Battery

I have a question...the dates on the initial notification and the C-141 do not match...which is correct?



- Release Location: Legal -9-23S-28E, API: 30-015-24424
- · Release Volume: 1 bbls of Oil and 263 bbls of Produced Water.
- Recovered: 80 bbls recovered

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist O&G Spill/Release Coordinator

Bureau of Land Management 620 E. Greene St Carlsbad. NM 88220

575.234.5905 - Direct 575.361.0084 - Cellular 575.234.6235 - Emergency Spill Number

stucker@blm.gov

The <u>BLM acceptance/approval does not</u> relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Mon, Sep 11, 2017 at 1:59 PM, < Wade Dittrich@oxy.com > wrote:

All,

This is to inform you that Oxy Permian had a **Reportable** release in **Eddy County** at the **NEL 4 SWD Battery** on 9/8/2017.

- Release Location: Legal -9-23S-28E, API: 30-015-24424
- Release Volume: 1 bbls of Oil and 263 bbls of Produced Water.
- Recovered: 80 bbls recovered
- Cause of Release: Pop off valve on relief line failure
- **Approximate Area impacted by release**: 80x80 FT, Leak did not leave the location-Leak is inside containment (measurements are subject to change with GPS tracking)
- GPS Coordinates and Driving Direction: 32.3218727,-104.0860443 FROM CARLSBAD NM GO SOUTH ON HWY 285
 TURN LEFT OR EAST ON HWY 31 GO TO NYMEYER RD TURN LEFT GO .5 MILE TO LOCATION

Please let me know if you have any questions.

Wade Dittrich

Environmental Coordinator
Oxy Permian-New Mexico
575.390.2828 cell
Wade Dittrich@Oxy.com