

AMENDED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**
☒ Initial Report ☐ Final Report

Name of Company	OXY USA, Inc.	Contact	Wade Dittrich
Address	P.O. Box 4294, Houston, TX 77210	Telephone No.	(575)390-2828
Facility Name	NEL 4 SWD Battery	Facility Type	Salt Water Disposal
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-015-24424

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	9	23S	28E	1980	N	720	E	Eddy

Latitude 32.3218727 Longitude -104.0860443 NAD83

NATURE OF RELEASE

Type of Release	Produced water & crude oil	Volume of Release	263 bbls Produced Water & 1 bbl Crude Oil	Volume Recovered	80 bbls
Source of Release	Pop-off valve on relief line	Date and Hour of Occurrence	9/8/2017, Time unknown	Date and Hour of Discovery	9/8/2017, 12:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher & Crystal Weaver - NMOCD; Shirley Tucker - BLM			
By Whom?	Wade Dittrich	Date and Hour 9/11/2017, 1:59 PM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Spill caused by failure of a pop-off valve on a relief line. The pop-off valve has been repaired.

Describe Area Affected and Cleanup Action Taken.*

The release was confined to the earthen containment surrounding the SWD battery, and the affected area inside the berm measured approximately 6,400 sq. ft. Remediation of the impacted area will be conducted in accordance with NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:		
Printed Name: Wade Dittrich			
Title: Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 4/20/2018 Phone: (575) 390-2828			

* Attach Additional Sheets If Necessary