

**TABLE 2
CHLORIDE FIELD TESTS**

**OXY USA, INC.
OSAGE 18 FEE COM 0001H
EDDY COUNTY, NEW MEXICO
NMOCD REF. #: 2RP-4334**



SAMPLE LOCATION	SAMPLE DEPTH (BGS)	SAMPLE DATE	SOIL STATUS	HACH QUANTAB
				CHLORIDE (mg/Kg)
NMOCD Recommended Remediation Action Level (RRAL)				600
SP-2 @ 1.5'	1.5'	9/6/2017	In-Situ	776
SP-2 @ 2'	2'	9/6/2017	In-Situ	660
SP-2 @ 4'	4'	9/6/2017	In-Situ	288
SP-2 @ 4.5'	4.5'	9/6/2017	In-Situ	204
SP-3 @ 1.5'	1.5'	9/6/2017	In-Situ	512
SP-3 @ 2'	2'	9/6/2017	In-Situ	320
SP-3 @ 2.5'	2.5'	9/6/2017	In-Situ	176
SP-4 @ 1'	1'	9/6/2017	In-Situ	3,860
SP-4 @ 1.5'	1.5'	9/6/2017	In-Situ	2,552
SP-4 @ 2'	2'	9/6/2017	In-Situ	836
SP-4 @ 2.5'	2.5'	9/6/2017	In-Situ	320
SP-4 @ 3'	3'	9/6/2017	In-Situ	152
SP-5 @ 1'	1'	9/6/2017	In-Situ	1,052
SP-5 @ 1.5'	1.5'	9/6/2017	In-Situ	4,180
SP-5 @ 2'	2'	9/6/2017	In-Situ	4,180
SP-5 @ 2.5'	2.5'	9/6/2017	In-Situ	4,180
SP-5 @ 4'	4'	9/6/2017	In-Situ	4,180
SP-5 @ 5.5'	5.5'	9/6/2017	In-Situ	152
SP-5 @ 5.5'	5.5'	5/31/2018	In-Situ	456
SP-7 @ 1.5'	1.5'	9/6/2017	In-Situ	6,224
SP-7 @ 2'	2'	9/6/2017	In-Situ	3,927
SP-7 @ 2.5'	2.5'	9/6/2017	In-Situ	152
SP-8 @ 1.5'	1.5'	9/6/2017	In-Situ	4,180
SP-8 @ 2'	2'	9/6/2017	In-Situ	3,024
SP-8 @ 2.5'	2.5'	9/6/2017	In-Situ	1,420
SP-8 @ 3'	3'	9/6/2017	In-Situ	3,860
SP-8 @ 3.5'	3.5'	9/6/2017	In-Situ	1,648
SP-8 @ 4'	4'	9/6/2017	In-Situ	<128
SP-10 @ 1.5'	1.5'	9/6/2017	In-Situ	356
SP-10 @ 2'	2'	9/6/2017	In-Situ	320
SP-10 @ 2.5'	2.5'	9/6/2017	In-Situ	260
SP-10 @ 3'	3'	9/6/2017	In-Situ	260
SP-10 @ 4'	4'	9/6/2017	In-Situ	<128
SP-11 @ 1.5'	1.5'	9/6/2017	In-Situ	128

**TABLE 2
CHLORIDE FIELD TESTS**

**OXY USA, INC.
OSAGE 18 FEE COM 0001H
EDDY COUNTY, NEW MEXICO
NMOCD REF. #: 2RP-4334**



SAMPLE LOCATION	SAMPLE DEPTH (BGS)	SAMPLE DATE	SOIL STATUS	HACH QUANTAB
				CHLORIDE (mg/Kg)
NMOCD Recommended Remediation Action Level (RRAL)				600
Wall 1a	2.5'	5/28/2018	In-Situ	<116
Wall 2a	2.5'	5/28/2018	In-Situ	<116
Wall 3a	2.5'	5/28/2018	In-Situ	488
Wall 3b	2.5'	6/14/2018	In-Situ	<116
Wall 4a	2.5'	5/28/2018	Excavated	1,884
Wall 4b	2.5'	5/28/2018	In-Situ	536
Wall 4c	2.5'	6/14/2018	In-Situ	1,128
Wall 4d	2.5'	6/14/2018	In-Situ	412
Wall 5a	1'	5/28/2018	In-Situ	1,884
Wall 5b	1'	6/14/2018	In-Situ	<116
Wall 6a	1'	5/29/2018	In-Situ	<116
Wall 7a	1'	5/29/2018	In-Situ	<116
Wall 8a	0.5'	5/29/2018	In-Situ	<116
Wall 9a	0.5'	5/29/2018	In-Situ	184
Wall 10a	0.5'	5/29/2018	In-Situ	<116
Wall 11a	0.5'	5/29/2018	In-Situ	<116
Wall 12a	0.5'	5/29/2018	In-Situ	<116
Wall 13a	0.5'	5/29/2018	In-Situ	184
Wall 14a	0.5'	5/29/2018	In-Situ	184
Wall 15a	2'	5/29/2018	In-Situ	268
Wall 16a	2'	5/29/2018	In-Situ	332
Wall 17a	2'	5/29/2018	In-Situ	392
Wall 18a	2'	5/29/2018	In-Situ	<116
Wall 19a	2'	5/29/2018	In-Situ	196
Wall 20a	2'	5/29/2018	Excavated	664
Wall 20b	2'	5/31/2018	In-Situ	128
Wall 21a	2'	5/29/2018	Excavated	1,208
Wall 21b	2'	5/31/2018	In-Situ	296
Wall 22a	2'	5/29/2018	In-Situ	224
Wall 23a	1'	5/29/2018	In-Situ	140
Wall 24a	1'	5/29/2018	In-Situ	196
Wall 25a	1'	5/30/2018	In-Situ	228
Wall 26a	1'	5/30/2018	In-Situ	372
Wall 27a	1'	5/30/2018	In-Situ	<128
Wall 28a	1'	5/30/2018	In-Situ	<128
Wall 29a	2'	5/30/2018	In-Situ	148
Wall 30a	2'	5/30/2018	In-Situ	<128
Wall 31a	2'	5/30/2018	In-Situ	200
Wall 32a	2.5'	5/30/2018	In-Situ	<128
Wall 33a	0.5'	5/30/2018	In-Situ	172
Wall 34a	2.5'	5/30/2018	In-Situ	<128
Wall 35a	2'	5/30/2018	Excavated	1,812
Wall 36a	2'	5/30/2018	In-Situ	128

**TABLE 2
CHLORIDE FIELD TESTS**

**OXY USA, INC.
OSAGE 18 FEE COM 0001H
EDDY COUNTY, NEW MEXICO
NMOCD REF. #: 2RP-4334**



SAMPLE LOCATION	SAMPLE DEPTH (BGS)	SAMPLE DATE	SOIL STATUS	HACH QUANTAB
				CHLORIDE (mg/Kg)
NMOCD Recommended Remediation Action Level (RRAL)				600
Wall 37a	4'	5/30/2018	Excavated	664
Wall 37b	4'	5/30/2018	Excavated	1,696
Wall 37c	4'	5/30/2018	Excavated	1,696
Wall 37d	4'	5/30/2018	In-Situ	172
Wall 37e	4'	5/30/2018	In-Situ	172
Wall 38a	2'	5/30/2018	In-Situ	<128
Wall 39a	0.5'	5/31/2018	In-Situ	<128
Wall 40a	4'	5/30/2018	In-Situ	3,024
Wall 40b	4'	6/14/2018	In-Situ	844
Wall 40c	4'	6/14/2018	In-Situ	200
Wall 41a	4'	5/30/2018	Excavated	3,024
Wall 41b	4'	5/31/2018	In-Situ	148
Wall 42a	4'	5/30/2018	Excavated	1,208
Wall 42b	4'	5/31/2018	In-Situ	504
Wall 42c	4'	6/14/2018	In-Situ	148
Wall 44a	4'	5/31/2018	In-Situ	<128

Concentrations in BOLD exceed the NMOCD RRAL