

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1810729251

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Permian LLC	Contact Callie Karrigan
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name: Cypress Fee 23 27 9 No. 002H	Facility Type Oil and gas production facilities

Surface: Owner: Fee	Mineral: Owner: Fee	API No.: 30-015-44374
---------------------	---------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	9	23S	27E	1664	South	549	West	Eddy

Latitude 32.31677158N Longitude -104.20183140W

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 15 barrels	Volume Recovered: 8 bbls
Source of Release: transfer pump	Date and Hour of Occurrence 04/01/2018 unknown	Date and Hour of Discovery 04/01/2018 08:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver and Mike Bratcher – Eddy County	
By Whom? Callie Karrigan	Date and Hour 04/02/2018 07:28 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
Not applicable.

Describe Cause of Problem and Remedial Action Taken.*

Operator reported a centerline bottle washout on the water transfer pump at the Cypress Fee 23 27 9 No. 002H facility. Approximately 15 bbls of produced water was released onsite around the parameter of the water transfer pump.

Describe Area Affected and Cleanup Action Taken.*

A vac truck recovered standing fluids and a surficial scrape was performed. Saturated material was removed and disposed at R360. Remediation was completed by delineation and excavation of affected soils, which were disposed of at an NMOCD approved facility. Confirmation samples were collected for lab analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Callie Karrigan</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Callie Karrigan	Approved by Environmental Specialist <i>Mike Bratcher</i>	
Title: HES Professional	Approval Date: 7/6/18	Expiration Date: N/A
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 6/29/2018 Phone: 405-202-1028 (cell) 575-297-0956 (office)	FINAL	

* Attach Additional Sheets If Necessary

2RP-4705