

Bratcher, Mike, EMNRD

From: Lowry, Joel <JLowry@trcsolutions.com>
Sent: Thursday, June 14, 2018 3:08 PM
To: Bratcher, Mike, EMNRD; Price, Henryetta
Cc: Rebecca Haskell (rhaskell@concho.com); Dakota Neel (DNeel2@concho.com); Sheldon Hitchcock; DeAnn Grant
Subject: 2RP-4351 & 2RP-4454 - GJ West Coop Unit #108 and GJ West Coop Unit #011
Attachments: _2RP-4351_4454 - GJ West Coop 108_011 - Soil Investigation Summary and Proposed Remediation Workplan.pdf

Please find attached the *Soil Investigation Summary and Proposed Remediation Workplan* that has been prepared for the GJ West Coop Unit #108 (2RP-4351) and GJ West Coop Unit #011 (2RP-4454). The sites are located adjacent to each other in Unit Letter "E", Section 28, Township 17 South, Range 29 East in Eddy County, New Mexico. Upon receiving NMOCD and BLM-approval, TRC is prepared to begin remediation activities as outlined in the attached *Workplan*. Upon completion of Remediation Activities, a *Remediation Summary and Risk-Based Soil Closure Request* will be prepared detailing field activities and laboratory analytical results from confirmation soil samples. If you have any questions or need any additional information, please feel free to contact Becky Haskell or myself by phone or email. Thanks!

Joel Lowry
Senior Project Manager



2771 Highway 214, Denver City, TX 79323
C: 432-466-4450

[LinkedIn](#) | [Twitter](#) | [Blog](#) | www.trcsolutions.com