

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB I 62253 89 22

OPERATOR

Initial Report Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	SUNDANCE 9 FEDERAL #3 CTB	Facility Type	CTB
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-27232

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	9	24S	31E	660	NORTH	660	WEST	EDDY

Latitude N 32.23692' Longitude W 103.78886' NAD83

NATURE OF RELEASE

Type of Release	PRODUCED WATER	Volume of Release	238 bbls	Volume Recovered	120 BBLS
Source of Release	Corrosion of a nipple on the water transfer line	Date and Hour of Occurrence	08/03/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	08/03/2016 @ 12:37 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Corrosion of a nipple on the water transfer line caused a 238 bbls leak of produced water. A vacuum truck recovered 120 bbls and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is 100 ft x 50 ft (measurements are subject to change with GPS tracking). Remediation was completed in accordance with the remediation plan approved by the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: 	
Title: ENVIROMENTAL SPECIALIST	Approval Date: 07/13/18	Expiration Date: N/A
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1-15-18 Phone: 575-390-2828	Like approval BLM	

* Attach Additional Sheets If Necessary

FINAL

2RP-3827