

Bratcher, Mike, EMNRD

From: Shoemaker, Mike <Mike.Shoemaker@dvn.com>
Sent: Wednesday, June 20, 2018 6:02 PM
To: Shelly Tucker
Cc: Bratcher, Mike, EMNRD; Fulks, Brett
Subject: RE: West Shugart 30 Federal 1_140BBL PW_11.3.2016 2RP-3991
Attachments: West Shugart 30 Federal 1.pdf

Shelly and Mike,

I apologize as this one has slipped through the cracks on me. We have been out and completed delineation and developed a work plan for this site. Attached is the work plan for your review and approval.

Please let me know if you have any further questions.

Thanks,

Mike Shoemaker
EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway
Artesia, New Mexico 88210
575-746-5566 Office
575-513-5035 Mobile



From: Shelly Tucker [mailto:stucker@blm.gov]
Sent: Tuesday, June 19, 2018 2:21 PM
To: Shoemaker, Mike <Mike.Shoemaker@dvn.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>
Subject: Re: West Shugart 30 Federal 1_140BBL PW_11.3.2016

I am working through some of my files. I need an update on this release. It is over 19 months old. I need a proposal within the next 30 days.

NOTE: LPC Timing Stipulations are in effect - from March 1st through June 15th. Please plan remedial activities accordingly. Check for African Rue...treat (before it gets out of control).

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. **In such an event a site does not achieve successful restoration, or future issues with contaminants are encountered, the operator will be asked to address these issues until they are fully mitigated and the location is successfully reclaimed.** In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Thu, Nov 10, 2016 at 7:20 AM DeLaRosa, Dana <Dana.DeLaRosa@dv.com> wrote:

Good afternoon,

Attached is the Initial C141 and GIS Image for the 140BBL Oil release that occurred on 11.3.2016. The red dot on the GIS Image represents the approximate origin of release.

Thank you and have a great day,

Dana DeLaRosa

Field Admin Support

Production

B-Schedule



Devon Energy Corporation

PO Box 250

Artesia, NM 88211

575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.