

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCD Received: 02/26/18

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

pAB1710736736

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	CEDAR CANYON 22 #1H	Facility Type	OIL WELL
Surface Owner	FEDERAL	Mineral Owner	FEDERAL
		API No.	30-015-40668

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	24S	29E	1980	SOUTH	1980	WEST	EDDY

Latitude\_N 32.2011642°\_ Longitude\_W -103.9744949°\_ NAD83

**NATURE OF RELEASE**

Type of Release	OIL & PRODUCED WATER	Volume of Release	100 bbls OIL 5 bbls PW	Volume Recovered	96 OIL / 4 PW bbls
Source of Release	LINE OVER PRESSURED	Date and Hour of Occurrence	3-31-2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER, NMOCD; CRYSTAL WEAVER, NMOCD; SHELLY STUCKER, BLM		
By Whom?	CASEY SUMMERS	Date and Hour	04/03/2017 12:30 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Line over pressured and caused PRV to open which over ran the tank. No high level alarm was set on tank. Oxy is looking into pressure and alarm issue to determine problem. Everything in line containment was recovered.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 35' x 15' and is both on and off location. Remediation was completed in accordance with a remediation plan approved by NMOCD (09/21/2017) and BLM (10/03/2017).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: <i>Maria Puett</i>		
Title: ENVIRONMENTAL SPECIALIST	Approval Date: 07/25/18	Expiration Date: N/A	
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval: Like Approval BLM	Attached <input type="checkbox"/>	
Date: 2-26-18 Phone: 575-390-2828			

\* Attach Additional Sheets If Necessary

FINAL

2RP-4173