

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office
in accordance with 19.15.29 NMAC..

Release Notification and Corrective Action

pAB1804027850

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: DIAMONDBACK 22 STATE COM #005H	Facility Type: Tank Battery
Surface Owner: State	Mineral Owner: State
API No. 30-015-42432	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	26S	28E	170	North	990	East	Eddy

Latitude 32.0348206 Longitude 104.069664

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 170 bbls PW	Volume Recovered: 160 bbls PW
Source of Release: Water Transfer Pump	Date and Hour of Occurrence: 2/4/2018	Date and Hour of Discovery: 2/4/2018 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver/NMOCD & Tammy Honea/NMSLO	
By Whom? Sheldon Hitchcock	Date and Hour: 2/5/2018 9:09 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release occurred when a plug on the water transfer pump fell out due to corrosion. The plug has been replaced.

Describe Area Affected and Cleanup Action Taken.*

The release remained inside of the lined containment. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: <i>Maria Pruett</i>	
Printed Name: Dakota Neel		
Title: HSE Coordinator	Approval Date: 07/27/18	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 3/5/2018 Phone: 575-746-2010		

* Attach Additional Sheets If Necessary

FINAL

2RP-4610