

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 8/03/2018  
NMOCD Dist 2

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

nAB1821154360

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: USP Fee #002	Facility Type: Tank Battery

Surface Owner: Private	Mineral Owner: State	API No.30-015-34438
------------------------	----------------------	---------------------

### LOCATION OF RELEASE

Unit Letter D	Section 16	Township 23S	Range 29E	Feet from the 319	North/South Line North	Feet from the 946	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.3115883 Longitude -103.9951782 NAD83

### NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 0.5 bbl. – Oil 10 bbl. – Produced Water	Volume Recovered: 0 bbl. – Oil 8 bbl. – Produced Water
Source of Release: Valve Malfunction	Date and Hour of Occurrence: July 9, 2018 3:00pm	Date and Hour of Discovery: July 9, 2018 3:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a ball valve on the flowline leaking. The line has been isolated and plugged.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined facility. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature: 		Approved by Environmental Specialist: 	
Printed Name: DeAnn Grant			
Title: HSE Administrative Assistant		Approval Date: 8/6/2018	Expiration Date: N/A
E-mail Address: agrant@concho.com		Conditions of Approval: N/A  FINAL	Attached <input type="checkbox"/>
Date: August 3, 2018 Phone: 432-253-4513			

\* Attach Additional Sheets If Necessary

2RP-4877