

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCD Rec'd:08/10/18

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | | | |
|-----------------|------------------------------------|---------------|---------------|----------------------|
| Name of Company | OXY USA INC | OGRID:16696 | Contact | WADE DITTRICH |
| Address | 1017 W. STANOLIND, HOBBS, NM 88240 | | Telephone No. | 575-390-2828 |
| Facility Name | FEDERAL 10 #1 | | Facility Type | BATTERY |
| Surface Owner | FEDERAL | Mineral Owner | FEDERAL | API No. 30-015-26649 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| | 10 | 23S | 28E | | | | | EDDY |

Latitude_32.321852_ Longitude_-104.080415_ NAD83

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|--|----------------------------|------------|
| Type of Release | PRODUCED WATER | Volume of Release | 200 BBLs PRODUCED WATER | Volume Recovered | 0 |
| Source of Release | 3 INCH POLY WATER LINE FAILURE | Date and Hour of Occurrence | 08/08/2018 | Date and Hour of Discovery | 08/08/2018 |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | MIKE BRATCHER-NMOCD; MARIA PURIT -NMOCD; SHELLY TUCKER-BLM | | |
| By Whom? | WADE DITTRICH | Date and Hour | 08/08/2018 | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a 3 Inch Poly Water Line Failure.

Describe Area Affected and Cleanup Action Taken.*

The affected area is 30x900ft (measurements are subject to change with GPS tracking). Remediation will be completed in accordance with a remediation plan approved by the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|--|----------------------|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | | |
| Printed Name: WADE DITTRICH | Approved by Environmental Specialist: Maria Pruett | | |
| Title: ENVIRONMENTAL SPECIALIST | Approval Date: 08/10/18 | Expiration Date: N/A | |
| E-mail Address: wade_dittrich@oxy.com | Conditions of Approval: | | Attached <input type="checkbox"/> |
| Date: 08/10/2018 | Phone: 575-390-2828 | 2RP-4910 | |

* Attach Additional Sheets If Necessary
A#:pMAP1822259859
I#:nMAP1822260952