

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD Rec'd: 08/15/18

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (217955)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443
Facility Name: Cottonmouth 23 Federal Com #002H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: Federal	API No. 30-015-43015
----------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	26S	28E	190	North	330	East	Eddy

Latitude 32.034786174 Longitude -104.06753455 NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 120 bbl.	Volume Recovered 119 bbl.
Source of Release Transfer Pump	Date and Hour of Occurrence August 15, 2018 11:00am	Date and Hour of Discovery August 15, 2018 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Marie Pruett – NMOCD Mike Bratcher – NMOCD Ryan Mann – SLO Shelly Tucker - BLM	
By Whom? DeAnn Grant	Date and Hour August 15, 2018 4:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The water transfer pump blew a seal due to high pressure. The pump is being inspected and the seal is being replaced.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: Maria Pruett	
Title: HSE Administrative Assistant		Approval Date: 08/17/18	Expiration Date: N/A
E-mail Address: agrant@concho.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: August 15, 2018 Phone: (432) 253-4513			2RP-4924

* Attach Additional Sheets If Necessary

A#: pMAP1822955044

I#: nMAP1822955161