




Note: Impacted soil located beneath the lined secondary containment will be remediated at time of abandonment of the tank battery.

**LEGEND:**

- ▲ Sidewall Sample
- Impacted Soil
- Floor Sample



**Figure 3**  
 Site Details & Confirmation  
 Soil Sample Locations Map  
 SRO STATE COM #064H  
 COG Operating, LLC.  
 Eddy County, NM

Scale: 1" = 66'	
CAD By: JH	Checked By: NG
November 30, 2017	
LAT. N 32.0576019 , Long. W 104.0815811	
SW 1/4 NW 1/4 SEC 10 T26S R28E	
TRC Proj. NO.: 279785	

2057 Commerce Drive  
 Midland, Texas 79703  
 432.520.7720