

From: [Pruett, Maria, EMNRD](#)
To: ["Karrigan, Callie N. \(MRO\)"; Bratcher, Mike, EMNRD](#)
Cc: [Heather Patterson; Castro, Isaac \(MRO\)](#)
Subject: 2RP-4956 C-141 Release Notification Received : Marathon Oil Company - Initial C141 Submittal - Iron Duke 2H
Date: Tuesday, September 4, 2018 6:02:00 PM

Hello Ms. Karrigan,

OCD has received your C-141 Release Notification, thank you! It has been assigned 2RP-4956. Please let me know if you have any questions.

Best Regards,

Maria Pruett

Environmental Specialist
N.M. Oil Conservation Division
District 2
811 S. 1st Street
Artesia, NM 88210
Desk: 575 748-1283 X 101
Cell: 575 840-5963
Fax: 575748-9720

From: Karrigan, Callie N. (MRO) <cnkarrigan@marathonoil.com>
Sent: Friday, August 31, 2018 11:08 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>
Cc: Heather Patterson <heather.patterson@soudermiller.com>; Castro, Isaac (MRO) <icastro@marathonoil.com>
Subject: Marathon Oil Company - Initial C141 Submittal - Iron Duke 2H

Good morning,

Please see the attached initial C141.

Thank you,

Callie

From: Karrigan, Callie N. (MRO)
Sent: Saturday, August 18, 2018 3:40 PM
To: 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'Pruett, Maria, EMNRD'

<Maria.Pruett@state.nm.us>

Subject: Marathon Oil Company - 24 hour notification - Iron Duke 2H

Good afternoon,

At approximately 8:45 am, the Operator arrived onsite and observed pooling from produced water. The ball valve on the load line leaked into the load out pot, releasing 10 bbls onto the ground. Approximately a 20 ft x 20 ft area was affected. A vac truck immediately recovered standing fluids. The ball valve will be replaced and investigated.

Callie Karrigan

HES Professional – Environmental

Office: 575-297-0956

Cell: 405-202-1028