

**From:** [DeAnn Grant](#)  
**To:** [Pruett, Maria, EMNRD](#); [Tucker, Shelly](#)  
**Cc:** [Bratcher, Mike, EMNRD](#); [jamos@blm.gov](mailto:jamos@blm.gov); [Dakota Neel](#); [DeAnn Grant](#); [Ike Tavarez](#); [Rebecca Haskell](#); [Robert McNeill](#); [Sheldon Hitchcock](#)  
**Subject:** [EXT] (C-141 Final) Screech Owl CTB (2RP-4966) 09-06-2018  
**Date:** Monday, October 22, 2018 7:01:37 AM  
**Attachments:** [image001.png](#)  
[image002.png](#)  
[\(C-141 Final\) Screech Owl CTB \(2RP-4966\) 09-06-2018.pdf](#)

---

Ms. Pruett/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

*DeAnn Grant*

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.