From:	Pruett, Maria, EMNRD
To:	"DeAnn Grant"
Cc:	Bratcher, Mike, EMNRD; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject:	2RP-4895 Closure Approved RE: [EXT] (C-141 Final) Copperhead Fee A #003H (30-015-42327) 07-31-2018
Date:	Tuesday, November 6, 2018 1:08:00 PM
Attachments:	image001.png
	image002.png

Hello Ms. Grant,

OCD has received the C-141 closure, thank you! The closure for 2RP-4895 is approved. Please note for future closures:

- 1. Please fill in spill identifiers in the C-141.
- 2. OCD needs a 2 business day notification on liner inspections.
- 3. If OCD cannot make the inspection please take GPS marked photos for closure.
- 4. OCD approved signage is necessary for these sites.

Please let me know if you have any questions.

Best Regards,

Maria Pruett

Environmental Specialist N.M. Oil Conservation Division District 2 811 S. 1st Street Artesia, NM 88210 Desk: 575 748-1283 X 101 Cell: 575 840-5963 Fax: 575748-9720

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>Sent: Wednesday, October 10, 2018 11:59 AMTo: Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Ike Tavarez <itavarez@concho.com>; Robert McNeill<RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>;Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>Subject: [EXT] (C-141 Final) Copperhead Fee A #003H (30-015-42327) 07-31-2018

Ms. Pruett,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant agrant@concho.com

COG Operating LLC 600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.