From: Pruett, Maria, EMNRD

To: "DeAnn Grant"; Tucker, Shelly

Cc: Bratcher, Mike, EMNRD; jamos@blm.gov; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca

<u>Haskell</u>

Subject: 2RP-5034 RE: (C-141 Initial) Copperhead 31 Federal Com #001H (30-015-38532) 10-21-2018

Date: Tuesday, November 6, 2018 11:26:00 AM

Attachments: <u>image001.png</u>

Hello Ms. Grant,

OCD has received the C-141 Release Notification, thank you! This has been assigned 2RP-5034.

Note at this location there are multiple spills including one area with contamination at 17′. Depending on results of a complete delineation, it may be necessary to install a ground water monitoring well. When a Remediation Plan and/or Closure is submitted please address how this facility will be modified to eliminate/reduce spills.

Please let me know if you have any questions or need further assistance.

Best Regards,

Environmental Specialist

Maria Pruett

N.M. Oil Conservation Division

District 2

811 S. 1st Street

Artesia, NM 88210

Desk: 575 748-1283 X 101

Cell: 575 840-5963 Fax: 575748-9720

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, November 1, 2018 4:06 PM

To: Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Tucker, Shelly <stucker@blm.gov> **Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; jamos@blm.gov; Ike Tavarez
<itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock
<SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell
<RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>

Subject: [EXT] (C-141 Initial) Copperhead 31 Federal Com #001H (30-015-38532) 10-21-2018

Ms. Pruett/Ms. Tucker,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the

volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeAnn Grant

HSE Administrative Assistant agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.