

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report



Name of Company: <b>COG Operating, LLC (OGRID# 229137)</b>	Contact: <b>Robert McNeill</b>	
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No.: <b>432-683-7443</b>	
Facility Name: <b>Patron 23 Federal #004H</b>	Facility Type: <b>Flowline</b>	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-42451

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	25S	29E	190	North	660	East	Eddy

Latitude: 32.127620 Longitude: -103.956767 NAD83

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 8bbls	Volume Recovered: 5bbls
Source of Release: Flowline	Date and Hour of Occurrence: 7/1/2017 10:00am	Date and Hour of Discovery: 7/1/2017 10:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A four-inch ball valve failed due to corrosion. The valve was replaced.		
Describe Area Affected and Cleanup Action Taken.* The release affected the pasture and adjacent lease road. COG had the site evaluated and submitted a remediation work plan that was subsequently approved by NMOCD and BLM. The remediation was carried out in accordance with the approved work plan and stipulations.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 11/14/18	Expiration Date:
E-mail Address: slhitchcock@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/17/2018	Phone: 575-746-2010	

\* Attach Additional Sheets If Necessary