

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

### Location of Release Source

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)


Cause of Release

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input type="checkbox"/> The source of the release has been stopped. <input type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: _____	Title: _____
Signature: _____	Date: _____
email: _____	Telephone: _____
<b><u>OCD Only</u></b> Received by:  _____ Date: _____	

**From:** [Bratcher, Mike, EMNRD](#)  
**To:** [Bustamante, Amalia, EMNRD](#)  
**Subject:** FW: [EXTERNAL] RE: Ice Dancer 30 Fed Com 2H - Spill 11/1/18  
**Date:** Tuesday, December 4, 2018 8:20:51 AM  
**Attachments:** [image002.png](#)  
[Ice Dancer 30 Federal Com 2H 30.151 BBLs Oil C-141 11.2.2018.pdf](#)

---

Amalia – I'm not sure what the change is. Maria had calculated this release to be 360 bbls, but I get pretty close to what they have listed when I do the calculation.

Thanks - MB

---

**From:** Davis, Amanda <Amanda.Davis@dvn.com>  
**Sent:** Monday, December 3, 2018 8:47 PM  
**To:** Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; stucker@blm.gov  
**Cc:** Fulks, Brett <Brett.Fulks@dvn.com>; DeHoyos, Kendra <Kendra.DeHoyos@dvn.com>  
**Subject:** [EXT] RE: [EXTERNAL] RE: Ice Dancer 30 Fed Com 2H - Spill 11/1/18

Ms. Purett,

Thank you for catching the error in our C-141. I have attached a corrected C-141 with the appropriate unit notation. If you have additional questions or concerns please feel free to contact me.

Thank you,

Amanda T. Davis  
Environmental Representative

Devon Energy Corporation  
6488 Seven Rivers Highway  
Artesia, New Mexico 88210  
(575) 748-0176 Direct  
(505) 350-1336 Mobile



---

**From:** Pruett, Maria, EMNRD [<mailto:Maria.Pruett@state.nm.us>]  
**Sent:** Friday, November 30, 2018 2:41 PM

**To:** DeHoyos, Kendra <[Kendra.DeHoyos@dyn.com](mailto:Kendra.DeHoyos@dyn.com)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov)  
**Cc:** Davis, Amanda <[Amanda.Davis@dyn.com](mailto:Amanda.Davis@dyn.com)>; Fulks, Brett <[Brett.Fulks@dyn.com](mailto:Brett.Fulks@dyn.com)>  
**Subject:** RE: [EXTERNAL] RE: Ice Dancer 30 Fed Com 2H - Spill 11/1/18

Hello Ms. DeHoyos,

Using the numbers provided, OCD estimates a spill volume of 360 bbls. Would you like us to adjust the volume on the sheet?

Best Regards,

*Maria Pruett*

Environmental Specialist  
N.M. Oil Conservation Division  
District 2  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Desk: 575 748-1283 X 101  
Cell: 575 840-5963  
Fax: 575748-9720

---

**From:** DeHoyos, Kendra <[Kendra.DeHoyos@dyn.com](mailto:Kendra.DeHoyos@dyn.com)>  
**Sent:** Thursday, November 29, 2018 4:18 PM  
**To:** Pruett, Maria, EMNRD <[Maria.Pruett@state.nm.us](mailto:Maria.Pruett@state.nm.us)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov)  
**Cc:** Davis, Amanda <[Amanda.Davis@dyn.com](mailto:Amanda.Davis@dyn.com)>; Fulks, Brett <[Brett.Fulks@dyn.com](mailto:Brett.Fulks@dyn.com)>  
**Subject:** [EXT] RE: [EXTERNAL] RE: Ice Dancer 30 Fed Com 2H - Spill 11/1/18

Attached is the corrected C-141.

Thank you,

*Kendra DeHoyos*  
EHS Associate  
Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211



**From:** Pruett, Maria, EMNRD <[Maria.Pruett@state.nm.us](mailto:Maria.Pruett@state.nm.us)>  
**Sent:** Wednesday, November 21, 2018 12:01 PM  
**To:** DeHoyos, Kendra <[Kendra.DeHoyos@dyn.com](mailto:Kendra.DeHoyos@dyn.com)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov)  
**Cc:** Davis, Amanda <[Amanda.Davis@dyn.com](mailto:Amanda.Davis@dyn.com)>; Fulks, Brett <[Brett.Fulks@dyn.com](mailto:Brett.Fulks@dyn.com)>  
**Subject:** [EXTERNAL] RE: Ice Dancer 30 Fed Com 2H - Spill 11/1/18

Hello Ms. DeHoyos,

Thank you for the C-141 form. Please send the spill calculations so we can process this permit. Let me know if you have any questions. Please also note, the other attachment is a Google Earth view of the site and not a GPS photo of the spill.

Best Regards,

*Maria Pruett*

Environmental Specialist  
N.M. Oil Conservation Division  
District 2  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Desk: 575 748-1283 X 101  
Cell: 575 840-5963  
Fax: 575748-9720

---

**From:** DeHoyos, Kendra <[Kendra.DeHoyos@dyn.com](mailto:Kendra.DeHoyos@dyn.com)>  
**Sent:** Wednesday, November 21, 2018 9:33 AM  
**To:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Pruett, Maria, EMNRD <[Maria.Pruett@state.nm.us](mailto:Maria.Pruett@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov)  
**Cc:** Davis, Amanda <[Amanda.Davis@dyn.com](mailto:Amanda.Davis@dyn.com)>; Fulks, Brett <[Brett.Fulks@dyn.com](mailto:Brett.Fulks@dyn.com)>  
**Subject:** [EXT] Ice Dancer 30 Fed Com 2H - Spill 11/1/18

Good Morning,

Please see the attached initial C-141 and GIS picture of the spill that occurred at the Ice Dancer 30 Fed Com 2H on 11/1/18.

Thank you,

*Kendra DeHoyos*

EHS Associate  
Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211



Devon - Internal

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.