

Bratcher, Mike, EMNRD

From: DeLeon, Josepha <JDxD@chevron.com>
Sent: Wednesday, January 2, 2019 3:27 PM
To: Tucker, Shelly
Cc: Bratcher, Mike, EMNRD; Pruett, Maria, EMNRD; James Amos; Barringer, Andrew J; Faulkner, Rick; Barnhill, Amy D.; Macurdy, David William
Subject: [EXT] RE: Re: [EXTERNAL] C141 - Lentini 19 Flowline Leak

Shelly, I apologize for delay in response to your email. The spill occurred on road crossing between wellhead and facility, unlined.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU
(Carlsbad, Hobbs, Eunice, Vacuum, Buckeye Gas Plant)
1616 W. Bender Blvd.
Hobbs, NM 88240
575-263-0424
432-425-1528 - cell
jdxd@chevron.com

From: Tucker, Shelly <stucker@blm.gov>
Sent: Tuesday, December 11, 2018 1:18 PM
To: DeLeon, Josepha <JDxD@chevron.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; James Amos <jamos@blm.gov>; Barringer, Andrew J <Andrew.Barringer@chevron.com>; Debeyessey, Svetlana <LDebeyessey@chevron.com>; Faulkner, Rick <Rick.Faulkner@chevron.com>; Barnhill, Amy D. <ABarnhill@chevron.com>; Macurdy, David William <david.macurdy@chevron.com>
Subject: [****EXTERNAL****] Re: [EXTERNAL] C141 - Lentini 19 Flowline Leak

Did this release occur within a lined facility, contained on location, or impacted off location?

If you have any questions or concerns, please do not hesitate to contact me.

Please be aware if you need to meet with me in person, I am currently working out of the Hobbs Field Office on a temporary basis. I will be in and out of both field offices. I am unsure at this time how long I will be based out of Hobbs. I can still be contacted at any of the numbers listed below.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. **In such an event a site does not achieve successful restoration, or future issues with contaminants are encountered, the operator will be asked to address these issues until they are fully mitigated and the location is successfully reclaimed.** In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

NOTE: LPC Timing Stipulations - from March 1st through June 15th. Please plan remedial activities accordingly. Check for African Rue...treat (before it gets out of control).

On Fri, Dec 7, 2018 at 1:54 PM DeLeon, Josepha <JDxD@chevron.com> wrote:

Attached is the C141 for spill that occurred at Lentini 19.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(Carlsbad, Hobbs, Eunice, Vacuum, Buckeye Gas Plant)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdxd@chevron.com

