

## Venegas, Victoria, EMNRD

---

**From:** DeAnn Grant <agrant@concho.com>  
**Sent:** Wednesday, January 30, 2019 9:31 AM  
**To:** Bratcher, Mike, EMNRD; Mann, Ryan; jamos@blm.gov  
**Cc:** Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Griswold, Jim, EMNRD; Tucker, Shelly; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant  
**Subject:** [EXT] (C-141 Final) Craig State #003H Battery (30-15-41971) 11-18-2018 (2RP-5106)  
**Attachments:** (C-141 Final) Craig State #003H Battery (30-15-41971) 11-18-2018 (2RP-5106).pdf

Mr. Bratcher/Mr. Mann/Mr. Amos,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

**DeAnn Grant**

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

