

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Wednesday, February 6, 2019 9:56 AM
To: 'DeAnn Grant'; Bratcher, Mike, EMNRD; Mann, Ryan; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD; Griswold, Jim, EMNRD; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Final) Craig State #003H Battery (30-15-41971) 11-18-2018 (2RP-5106)
Attachments: (C-141 Final) Craig State #003H Battery (30-15-41971) 11-18-2018 (2RP-5106).pdf

RE: 2RP-5106

Ms. Grant,

We have received your closure request for 2RP-5106, thank you. This closure is approved. Federal site will require BLM approval.

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Wednesday, January 30, 2019 9:31 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; Tucker, Shelly <stucker@blm.gov>; dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Final) Craig State #003H Battery (30-15-41971) 11-18-2018 (2RP-5106)

Mr. Bratcher/Mr. Mann/Mr. Amos,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

