Venegas, Victoria, EMNRD

From:	DeAnn Grant <agrant@concho.com></agrant@concho.com>
Sent:	Tuesday, February 5, 2019 4:08 PM
То:	Bratcher, Mike, EMNRD; Mann, Ryan
Cc:	Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Jennifer Knowlton; Ike Tavarez;
	Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject:	[EXT] (C-141 Final) SRO State #062H (30-015-42099) 1-17-2019 (2RP-5217)
Attachments:	(C-141 Final) SRO State #062H (30-015-42099) 1-17-2019 (2RP-5217).pdf

Mr. Bratcher/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeArnv Grant HSE Administrative Assistant agrant@concho.com COG Operating LLC 600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443

