

Venegas, Victoria, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Friday, February 1, 2019 7:44 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Tucker, Shelly; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject: [EXT] (Resubmittal) (C-141 Final) Cabo Wabo 25 Federal Com #003H (30-015-42507) 09-18-2018 (2RP-4981)
Attachments: (C-141 Final) Cabo Wabo 25 Federal Com #003H (30-015-42507) 09-18-2018.pdf; (C-141 Final) Cabo Wabo 25 Federal Com #003H (30-015-42507) 09-18-2018 (2RP-4981)

Mr. Bratcher/Mr. Amos,

Please find the attached Closure Request for the COG Cabo Wabo 25 Federal Com #003H (2RP-4981) (30-015-42507) release which occurred on 9/18/18. The closure request was originally submitted to the NMOCD District 2 Office on December 3, 2018. COG is requesting that you review this closure request.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701


Direct: 432-253-4513 | Main: 432.683.7443



From: DeAnn Grant
Sent: Monday, December 03, 2018 10:02 AM
To: 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; Tucker, Shelly <stucker@blm.gov>
Cc: Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: (C-141 Final) Cabo Wabo 25 Federal Com #003H (30-015-42507) 09-18-2018 (2RP-4981)

Mr. Bratcher/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

