

Location:	JRU #10 Battery (30-015-23075)	
Spill Date:	1/29/2019	
Length of Spill=	42.00	feet
Width of Spill=	19.00	feet
Saturation (or depth) of Spill=	8.00	inches
Approximate Oil %	100	
Porosity Factor=	0.03	
Volume Recovered=	7.00	bbls

VOLUME OF LEAK		
Total Oil=	9.8	barrels
Total Produced Water=	-	barrels

VOLUME RECOVERED		
Total Oil=	7	barrels
Total Produced Water=	-	barrels