District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsibly Party

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District Office

Incident ID	0 NAB1905154793
District RP	0 1RP-5373
Facility ID	0 fAB1905154644
Application ID	0 pAB1905154398

371183

Release Notification Responsible Party

OGRID

ETC Texas Pipeline, Ltd.

Contact Name	Carolyn Bla	ckaller	Contact Telep	hone	817-302-97	66	
Contact Email	mail carolyn.blackaller@energytransfer.c Incident # (as			igned by OCD	NAB19051547	93	
Contact Mailing Address 600 N. Marienfeld. St., Suite 700, Midland, TX 79701							
Location of Release Source							
Latitude	32.13801		Longitude		-103.20197		
(Nad 83 in decimal degrees to 5 decimal places)							
Site Name 2B-2			Site Type		Pipeline		
Date Release Discovered	02/04/19		API# (if applic	able) NA			
					· 		
Unit Letter Section	Township	Range	County	/			
N 7	T25S	R37E	Lea				
Surface Owner: State Federal Tribal Private (Name Fulfer Investments) Nature and Volume of Release							
Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oil	Volume Released (bbls)		Volume Recovered (bbls)				
Produced Water	er Volume Released (bbls)		Volume Recovered (bbls)				
Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?		Yes	No V N/A				
☐ Condensate	Condensate Volume Released (bbls)		Volume Rec	overed (bbls)			
Natural Gas Volume Released (Mcf) 107.173 Mcf		Volume Rec	overed (Mcf)	None			
Other (describe) Volume/Weight Released (provide units)		Volume/Wei	ight Recovered (provi	de units)			
Cause of Release	•						
The release was attributed to the failure of a segment of buried natural gas pipeline as a result of corrosion.							

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	0 NAB1905154793
District RP	0 1RP-5373
Facility ID	0 fAB1905154644
Application ID	0 pAB1905154398

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsit	ole party conside	er this a major release?			
☐ Yes ☑ No						
If YFS was immediate a	notice given to the OCD? By whom? To who	n? When and by	what means? (phone, amail, atc)?			
ii 125, was iiiiiiculate i	ionee given to the OCD: By whom: To who	ii: When and by	what means: (phone, eman, etc):			
Initial Response						
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury						
✓ The source of the re	elease has been stopped.					
	has been secured to protect human health and	the environment				
· _ ·	ave been contained via the use of berms or dil					
☑ All free liquids and	recoverable materials have been removed and	l managed appro	priately.			
If all the actions describe	ed above have <u>not</u> been undertaken, explain w	hy:				
			diately after discovery of a release. If remediation			
			ccessfully completed or if the release occurred			
within a lined containment area (see 19.15.29.11 (A)(5)(a) NMAC), please attach all information needed for closure evaluation. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and						
			form corrective actions for releases which may endanger			
public health or the enviro	nment. The acceptance of a C-141 report by the C	OCD does not reli	eve the operator of liability should their operations have			
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws						
addition, OCD acceptance and/or regulations.	of a C-141 report does not relieve the operator of	responsibility to	r compliance with any other federal, state, or local laws			
Printed Name:	Carolyn Blackaller	Title:	Sr. Environmental Specialist			
Signature:	wlmepacka0000	Date:	2/15/2019			
	00					
email: <u>carolyn.blac</u>	kaller@energytransfer.com	Telephone:	817-302-9766			
OCD Only /						
Received by:	ant Intamente	Date:	2/20/2019			
/						