

| | | |
|--|-----------------------------|--------|
| Location: | BEU DI2 323H (30-015-43648) | |
| Spill Date: | 2/21/2019 | |
| Length of Spill= | 55.00 | feet |
| Width of Spill= | 40.00 | feet |
| Saturation (or depth) of Spill= | 2.00 | inches |
| Approximate Oil % | - | |
| Porosity Factor= | 0.03 | |
| Volume Recovered= | 3.00 | bbls |

| VOLUME OF LEAK | | |
|------------------------------|-----|---------|
| Total Oil= | - | barrels |
| Total Produced Water= | 5.0 | barrels |

| VOLUME RECOVERED | | |
|------------------------------|-----|---------|
| Total Oil= | - | barrels |
| Total Produced Water= | 3.0 | barrels |