

Location:	JRU 111H (30-015-38120)	
Spill Date:	3/9/2019	
Length of Spill=	85.00	feet
Width of Spill=	65.00	feet
Saturation (or depth) of Spill=	2.00	inches
Approximate Oil %	40	
Porosity Factor=	0.03	
Volume Recovered=	1.00	bbls

VOLUME OF LEAK		
Total Oil=	2.4	barrels
Total Produced Water=	3.6	barrels

VOLUME RECOVERED		
Total Oil=	0.4	barrels
Total Produced Water=	0.6	barrels