

Location:	Avalon Delaware Unit 562 (30-015-24377)	
Spill Date:	3/9/2019	
Length of Spill=	75.00	feet
Width of Spill=	60.00	feet
Saturation (or depth) of Spill=	2.00	inches
Approximate Oil %	-	
Porosity Factor=	0.03	
Volume Recovered=	1.00	bbls

VOLUME OF LEAK		
Total Oil=	-	barrels
Total Produced Water=	5.0	barrels

VOLUME RECOVERED		
Total Oil=	-	barrels
Total Produced Water=	1.0	barrels