Form C-141

Page 6

Oil Conservation Division State of New Mexico

Incident ID	
District RP	2RP-5168
Facility ID	
Application ID	

Closure

or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC. The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions

Closure approval by the OCD does not relieve the responsible party of liability she remediate contamination that poses a threat to groundwater, surface water, human learnly of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: CLOSURE IS NOT APPROVED Da Printed Name: DEFERRAL APPROVED Tile	email: Cesar_Ochoa @Kindermorgan.com OCD Only Victoria Venegas	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for release may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantia restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name: Date: 3/27/2019	Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling) Description of remediation activities	Closure Report Attachment Checklist: Each of the following items must be included in the closure report A scaled site and sampling diagram as described in 19.15.29.11 NMAC Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: apmust be notified 2 days prior to liner inspection)
be:	1 2 1	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19,15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name: Description Printed Name Pri	© District office must be notified 2 days prior to final sampling)	Closure Report Attachment Checklist: Each of the following items must be included in the closure report. A scaled site and sampling diagram as described in 19.15.29.11 NMAC Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

area, contaminated soil at these two points is still in place samples were collected. Due to infrastructure problems in the vicinity of the S-5 and S-11 sample EPNG only gathered samples at the area below the exhaust pad (16ft x 4ft) were S-11 and S-5