

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Tuesday, April 16, 2019 7:52 AM
To: 'DeAnn Grant'; Bratcher, Mike, EMNRD
Cc: Hamlet, Robert, EMNRD; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Final) Copperhead 31 Fee #020H Battery 01-19-2019 (2RP-5219)
Attachments: (C-141 Final) Copperhead 31 Fee #020H Battery 4.16.19.pdf

: [EXT] (C-141 Final) Copperhead 31 Fee #020H Battery 01-19-2019 (**2RP-5219**)

Ms. Grant,
OCD has received your closure request and final C-141 for Copperhead 31 Fee #020H Battery 01-19-2019 (**2RP-5219**), thank you. This closure is approved.
Regards,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Monday, April 15, 2019 4:32 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Final) Copperhead 31 Fee #020H Battery 01-19-2019 (2RP-5219)

Mr. Bratcher,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

