District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party							
Responsible Party: Lime Rock Resources II-A, L.P.		OGRID 277558					
Contact Name: Mike Barrett			Contact Te	elephone 575.30	65.9724		
Contact ema	il: mbarrett(@limerockresourc	es.com		Incident #	2RP-5345	
Contact mail	ing address:	1111 Bagby Stre	et, Suite 4600, Ho	uston, T	TX 77002		
Location of Release Source							
Latitude 32.	743721				_Longitude		2
			(NAD 83 in d	ecimal de	grees to 5 dec	cimal places)	
Site Name:	Atoka San A	ndreas Unit #149			Site Type	: Oil Well	
Date Releas	e Discovered	d: 10/8/18			API# (if ap	pplicable) 30-015-0	0204
Unit Letter	Section	Township	Range		Coun	ats.	1
O	14	18S	26E		Edd		
Surface Owner: State Federal Tribal Private (Name: Martin Farms Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oil		Volume Release			•	Volume Reco	
Noduced Produced	Water	Volume Release	d (bbls) 17			Volume Reco	vered (bbls) 13
		Is the concentrat produced water	ion of dissolved cl >10,000 mg/l?	hloride	in the	Yes N	0
Condensa	te .	Volume Released (bbls)			Volume Reco	vered (bbls)	
☐ Natural G	as	Volume Released (Mcf)			Volume Reco	vered (Mcf)	
Other (des	scribe)	Volume/Weight Released (provide units)			Volume/Weig	ht Recovered (provide units)	
Cause of Release: A 3-inch flow line split causing mixed fluids (oil and water) to be released and pool in a low area of the draw. The line was immediately shut in and isolated. Remediation activities were immediately undertaken due to the fact that a large scale rain event could have the potential to shed contaminants from the (dry) draw into the Pecos River. The line was entirely replaced and put back into service upon completion of remediation activities.							

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	A 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the respon	nsible party consider this a major release?
19.15.29.7(Λ) NMÁC?		
☐ Yes ⊠ No		
If VES, was immediate no	ntice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
II 113, was ininequate no	once given to the OCD? By whom? To wi	om? when and by what means (phone, eman, etc)?
	Initial F	Response
The responsible	party must undertake the following actions immediat	ely unless they could create a safety hazard that would result in injury
☐ The source of the rele	ase has been stopped.	
☐ The impacted area has	s been secured to protect human health and	the environment.
Released materials ha	ve been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.
-	coverable materials have been removed and	
If all the actions described	l above have <u>not</u> been undertaken, explain v	vhy:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name: Mike I	Barrett /	Title: Production Superintendent
Signature:	1,54	Date: 10/19/18
email: mbarrette@li	imerockresources.com	Telephone: 575-365-9724
OCD O. I.		
OCD Only		
Received by:		Date:

State of New Mexico Oil Conservation Division

What is the shallowest depth to groundwater beneath the area affected by the release?

Incident ID	
District RP	
Facility ID	
Application ID	

(ft bgs)

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

Are the lateral extents of the release within 300 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)? Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church? Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.	Did this release impact groundwater or surface water?	☐ Yes ☒ No		
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church? Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographsi including date and GIS information	Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	Yes No		
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographic/Aerial maps	Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ⊠ No		
by less than five households for domestic or stock watering purposes? Are the lateral extents of the release within 1000 feet of any other fresh water well or spring? Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ⊠ No		
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographic/Aerial maps	Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ⊠ No		
water well field? Are the lateral extents of the release within 300 feet of a wetland? Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ⊠ No		
Are the lateral extents of the release overlying a subsurface mine? Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ⊠ No		
Are the lateral extents of the release overlying an unstable area such as karst geology? Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☒ No		
Are the lateral extents of the release within a 100-year floodplain? Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ⊠ No		
Did the release impact areas not on an exploration, development, production, or storage site? Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ⊠ No		
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics. Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Are the lateral extents of the release within a 100-year floodplain?	⊠ Yes □ No		
Characterization Report Checklist: Each of the following items must be included in the report. Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Did the release impact areas not on an exploration, development, production, or storage site?			
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps	Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.			
 □ Field data □ Data table of soil contaminant concentration data □ Depth to water determination □ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release □ Boring or excavation logs □ Photographs including date and GIS information □ Topographic/Aerial maps 	Characterization Report Checklist: Each of the following items must be included in the report.			
Laboratory data including chain of custody	 □ Field data □ Data table of soil contaminant concentration data □ Depth to water determination □ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release □ Boring or excavation logs □ Photographs including date and GIS information 			
	Laboratory data including chain of custody	,		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

State of New Mexico Oil Conservation Division

	1
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

The state of the s	
Remediation Plan Checklist: Each of the following items must b	e included in the plan.
Detailed description of prepared remodiation technique	
 Detailed description of proposed remediation technique Scaled sitemap with GPS coordinates showing delineation poin 	to
Estimated volume of material to be remediated	ts .
Closure criteria is to Table 1 specifications subject to 19.15.29.	12(C)(A) NM A C
Proposed schedule for remediation (note if remediation plan tin	
Troposed schedule for remediation (note if remediation plan till	terme is more than 50 days OCD approval is required)
<u>Deferral Requests Only</u> : Each of the following items must be con	nfirmed as part of any request for deferral of remediation.
$\hfill \Box$ Contamination must be in areas immediately under or around p deconstruction.	roduction equipment where remediation could cause a major facility
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human health	h, the environment, or groundwater.
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name: Mike Barrett	Title: Production Superintendent
Signature: MM Signature:	Date: 2/28/19
email: mbarrett@limerockresources.com	Telephone: 575.365.9724
	`
OCD Only	
Received by:	Date:
Approved	Approval Denied Deferral Approved
Signature:	Date:

State of New Mexico Oil Conservation Division

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

A scaled site and sampling diagram as described in 19.15.29.11 NMA		
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
☐ Laboratory analyses of final sampling (Note: appropriate ODC District	office must be notified 2 days prior to final sampling)	
Description of remediation activities		
Signature: Date: 2	notifications and perform corrective actions for releases which report by the OCD does not relieve the operator of liability ontamination that pose a threat to groundwater, surface water, report does not relieve the operator of responsibility for the responsible party acknowledges they must substantially that existed prior to the release or their final land use in a reclamation and re-vegetation are complete.	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by:	Date:	
Printed Name:	Title:	