From:	Tucker, Shelly
To:	Menoud, Denise
Cc:	Griswold, Jim, EMNRD; Bratcher, Mike, EMNRD; Pruett, Maria, EMNRD; Fulks, Brett
Subject:	Re: [EXTERNAL] Initial C141 - Lusitano 27-34 FC 235H - Spill 9/5/18
Date:	Friday, September 21, 2018 12:50:45 PM

MICRO NEPA

Please be aware of the following items prior to any excavation activities.

1. The release point did not impact any known archaeological area.

2. The point of release occurred on and off location but is **covered under a previous survey**, no additional surveys will be required.

3. This area is located within a **Medium cave/karst zone**.

4. This site is cleared of flood zones, active playas, but near an intermittent stream, etc.

5. Area is noted to be within **0-3% slope**.

6. Soils are within the **Berino complex**

7. BLM Seed Mix #2 (Sand mix) will be required.

8. The site is **NOT** located in DSL habitat or LPC habitat. No other T&E species noted (animal or vegetative) within this area.

9. Site is not located within Potash

10. Site is not located within a Special Area of concern.

11. Site is **not** located within a RMP ACEC.

12. Site is **not** located within Special Status Plant Species area.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist O&G Spill/Release Coordinator

575.234.5905 - Direct 575.361.0084 - Cellular 575.234.6235 - Emergency Spill Number

stucker@blm.gov

Bureau of Land Management 620 E. Greene St Carlsbad, NM 88220

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. <u>In such an event a site does not achieve successful restoration, or future issues with</u> <u>contaminants are encountered, the operator will be asked to address these issues until they are fully mitigated and the</u> <u>location is successfully reclaimed</u>. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

NOTE: LPC Timing Stipulations - from **March 1st through June 15th**. Please plan remedial activities accordingly. Check for African Rue...treat (before it gets out of control). On Thu, Sep 20, 2018 at 10:25 AM Menoud, Denise <<u>Denise.Menoud@dvn.com</u>> wrote:

Please see attached Initial C-141 for the spill that occurred on 9/5/18 at the Lusitano 27-34 FC 235H location. Thank you. Denise Menoud Admin Field Support, Completions - Reclamations - Regulatory Office: 575-746-5544 Email: denise.menoud@dvn.com Devon Energy 6488 Seven Rivers Hwy PO Box 250, Artesia, NM 88210 575-748-3371

Devon - Internal

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.