

Location:	Palmillo State #001H (30-015-23164)	
Spill Date:	4/1/2019	
Length of Spill=	36.00	feet
Width of Spill=	21.00	feet
Saturation (or depth) of Spill=	5.00	inches
Approximate Oil %	7	
Porosity Factor=	0.15	
Volume Recovered=	4.00	bbls

VOLUME OF LEAK		
Total Oil=	0.9	barrels
Total Produced Water=	11.5	barrels

VOLUME RECOVERED		
Total Oil=	0.3	barrels
Total Produced Water=	3.7	barrels