Venegas, Victoria, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, May 7, 2019 6:56 AM

To: Bratcher, Mike, EMNRD; Weaver, Crystal (caweaver@blm.gov)

Cc: Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; McKinney, Deborah;

jamos@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock;

Dakota Neel; Rebecca Haskell; DeAnn Grant

Subject: [EXT] (C-141 Final) Dodd Federal #14A Tank Battery 2-8-2019 (2RP-5239) **Attachments:** (C-141 Final) Dodd Federal #14A Tank Battery 2-8-2019 (2RP-5239).pdf

Mr. Bratcher/Ms. Weaver,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443



