

* SPILL WAS APPROX. 19 BBLS OF OIL. 18 BBLS STAYED INSIDE BURM AND APPROX. 1 BBL BLEW OUT ONTO CALICHE LOCATION. 10 BBLS OF FREE OIL SUCKED UP AND PUT BACK INTO TANKS. FENCE WAS TAKEN DOWN AND DIRT & GRAVEL WAS DUG OUT WITH BACKHOE AND PLACED ONTO PLASTIC LINER TO BE HAULED TO GANDY MARLEY SOLID WASTE DISPOSAL. CONTAMINATED SOIL OUTSIDE BATTERY WAS ALSO DUG UP AND PLACED ONTO LINER & WILL BE PROPERLY DISPOSED OF. FRESH CALICH WAS PLACED BACK ONTO LINER INSIDE BATTERY AND BURM PUT BACK UP. WILL PROVIDE PICTURES OF INTACT LINER INSIDE BURM AND WILL COLLECT SAMPLES OUTSIDE BURM TO DELINIATE BACK TO PROPER LEVELS.

THANK YOU, KIRK FARIES