Form C-141 Page 3

State of New Mexico Oil Conservation Division

What is the shallowest depth to groundwater beneath the area affected by the release?

Incident ID	NAB1914258619
District RP	2RP-5441
Facility ID	
Application ID	pAB1914258282

50-100 (ft. bgs)

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discover date.

Did this release impact groundwater or surface water?	☐ Yes ✓ No				
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ✓ No				
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☑ No				
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ✓ No				
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ✓ No				
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☑ No				
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☑ No				
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☑ No				
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ✓ No				
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☑ No				
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☑ No				
Did the release impact areas not on an exploration, development, production or storage site?	✓ Yes ☐ No				
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vert contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.	ical extents of soil				
Characterization Report Checklist: Each of the following items must be included in the report.					
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.					
Field data					
Data table of soil contaminant concentration data					
Determination of water sources and significant watercourses within 1/2-mile of the lateral extents of the release Boring or excavation logs	;				
Photographs including date and GIS information					
Thotographs including date and GIS information Topographic/Aerial maps					
☐ Laboratory data including chain of custody					

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. Than plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modifies by site- and release-specific parameters.

Form C-141 Page 4

State of New Mexico Oil Conservation Division

Incident ID	NAB1914258619
District RP	2RP-5441
Facility ID	
Application ID	pAB1914258282

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

3		EHS Representative	
ATDavis	Date:	5/21/2019	
manda.Davis@DVN.com	Telephone:	575-748-0176	
Anglie Textamente	Date:	5/22/2019	
	manda.Davis@DVN.com	manda.Davis@DVN.com Telephone:	manda.Davis@DVN.com Telephone: 575-748-0176