Form C-141 Page 5

## State of New Mexico Oil Conservation Division

Remediation Plan Checklist: Each of the following items must be included in the report.

Incident ID	NAB1914258619		
District RP	2RP-5441		
Facility ID			
Application ID	pAB1914258282		

## **Remediation Plan**

<ul> <li>✓ Detailed description of proposed remediation technique</li> <li>✓ Scaled sitemap with GPS coordinates showing delineation points</li> <li>✓ Estimated volume of material to be remediated</li> <li>✓ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC</li> <li>✓ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)</li> </ul>						
Deferral Requ	ests Only: Each of the following items must be confir	med as part	of any request for deferi	ral of remediation.		
Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.						
Extents of contamination must be fully delineated.						
Contamination does not cause an imminent risk to human health, the environment, or groundwater.						
which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name:  Amanda T. Davis  Title:  EHS Representative						
Signature:	ATDavis	Date:	5/21/2019	_		
email:	Amanda.Davis@DVN.com	Telephone	: 575-748	-0176		
OCD Only						
Received by:	Robert Hamlet	Date:	5/23/2019	_		
Approved	Approved with Attached Conditions of A		☐ Denied 5/23/2019	☐ Deferral Approved		
Signature:	<u> </u>	Date:	3/23/2019			