

## Venegas, Victoria, EMNRD

---

**From:** DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Sent:** Friday, May 24, 2019 9:45 AM  
**To:** Bratcher, Mike, EMNRD; [caweaver@blm.gov](mailto:caweaver@blm.gov); Mann, Ryan  
**Cc:** [jamos@blm.gov](mailto:jamos@blm.gov); [dmckinne@blm.gov](mailto:dmckinne@blm.gov); Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant; Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD  
**Subject:** [EXT] (C-141 Final) Craig State Com #001H (30-015-37466) 2-26-2019 (2RP-5308)  
**Attachments:** (C-141 Final) Craig State Com #001H (30-015-37466) 2-26-2019 (2RP-5308).pdf

Mr. Bratcher/Ms. Weaver/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

**DeAnn Grant**

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



