

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Monday, June 3, 2019 11:23 AM
To: 'DeAnn Grant'; Bratcher, Mike, EMNRD
Cc: Hamlet, Robert, EMNRD; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Final) Copperhead 31 Federal #003H (30-015-43924) 03-10-2019 (2RP-5325)
Attachments: (C-141 Final) Copperhead 31 Federal #003H (30-015-43924) 03-10-2019 (2RP-5325).pdf

RE: (C-141 Final) Copperhead 31 Federal #003H (30-015-43924) 03-10-2019 (2RP-5325)

Ms. Grant,
OCD has received your closure request and final C-141 for RE: (C-141 Final) Copperhead 31 Federal #003H (30-015-43924) 03-10-2019 (**2RP-5325**), thank you. This closure is approved.
Regards,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Monday, June 3, 2019 10:51 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; DeAnn Grant <agrant@concho.com>; Rebecca Haskell <RHaskell@concho.com>
Subject: [EXT] (C-141 Final) Copperhead 31 Federal #003H (30-015-43924) 03-10-2019 (2RP-5325)

Mr. Bratcher/Mr. Amos,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

